



KM08MYB

report date: 2024-03-29

General information

Make	VOLVO
Model	S40
Colour	Silver
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-18
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	25
Total items failed	15

MOT #18	2023-09-13 13:48
MOT test number	952623795598
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Front Exhaust mounting defective down pipe (6.1.2 (a))

MOT #17	2022-09-14 11:28
MOT test number	304579408181
Result	✓ Passed

MOT #16	2022-09-13 10:34
MOT test number	510024251264
Result	✗ Failed
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Nearside Front marker lamp inoperative
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Offside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))
Fail	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Nearside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))

**MOT #15** 2021-09-15 13:31**MOT test number** 986541253120**Result** ✓ Passed**MOT #14** 2021-07-13 08:24**MOT test number** 739481125565**Result** ✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear bushes on the o/s/f and n/s/f lower arms are starting to perish/worn (5.3.4 (a) (i))

**Advice** Front Brake pad(s) wearing thin brake pads are starting to wear on o/s/f and n/s/f (1.1.13 (a) (ii))

**MOT #13** 2020-07-07 09:25**MOT test number** 825167740693**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge heavy wear to inner and outer edges (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge very aggressive wear to inner edge and on the BORDERLINE of limit (5.2.3 (e))

**MOT #12** 2019-05-04 11:53**MOT test number** 806918779986**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Towball/hitch not fitted at time of test

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11**

2019-05-03 15:10

**MOT test number**

505972210285

**Result****✗ Failed**

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Fail** Offside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

**Advice** Towball/hitch not fitted at time of test

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10**

2019-03-28 09:28

**MOT test number**

685056485032

**Result****✗ Failed**

**Advice** Offside rear tyre cracking on outer edge

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside front tyre wearing on inner edge

**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #9** 2018-03-24 10:11**MOT test number** 904350045949**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-04-03 09:23**MOT test number** 673785703437**Result** ✓ Passed**Advice** Offside Rear Lower Rear reflector slightly damaged but function not impaired (1.5.1c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-04-04 12:35**MOT test number** 757193222127**Result** ✓ Passed**MOT #6** 2016-03-24 11:50**MOT test number** 342621258924**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2015-03-28 11:41**MOT test number** 437117785096**Result** ✓ Passed



MOT #4 2014-01-31 09:24

MOT test number 775671634046

Result ✓ Passed

MOT #3 2013-03-15 12:07

MOT test number 966434573010

Result ✓ Passed

**Notice** Items removed from driver's view prior to test

**Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2 2012-03-21 11:05

MOT test number 186801382438

Result ✓ Passed

MOT #1 2011-03-14 15:00

MOT test number 329833071019

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
14 September 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	14 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-10
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2008-04-10	6 mi
Registration #2	2011-03-14	18.021 mi
Registration #3	2012-03-21	23.765 mi
Registration #4	2013-03-15	28.179 mi
Registration #5	2014-01-31	32.276 mi
Registration #6	2015-03-28	38.979 mi
Registration #7	2016-03-24	44.447 mi
Registration #8	2016-04-04	44.698 mi
Registration #9	2017-04-03	49.408 mi
Registration #10	2018-03-24	53.192 mi
Registration #11	2019-03-20	55.377 mi
Registration #12	2019-03-20	55.377 mi
Registration #13	2019-03-20	55.377 mi
Registration #14	2019-03-20	55.377 mi
Registration #15	2019-03-20	55.377 mi
Registration #16	2019-03-20	55.377 mi
Registration #17	2019-03-20	55.377 mi
Registration #18	2019-03-20	55.377 mi
Registration #19	2019-03-20	55.377 mi
Registration #20	2019-03-20	55.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	4
Engine number	143891