





report date: 2024-03-28

General information

Make	CITROEN
Model	C3 PICASSO PURETECH PLATINUM PICASSO
Colour	Grey
Year of manufacture	2016
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

E ~	+	, 1
	ILI V	, .

Liid y I	
Date	2021-11-26
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



CV66HTU

report date: 2024-03-28

MOT history

MOT expiry date	2024-12-03
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #8	2023-11-29 14:30
MOT test number	764506998622
Result	✓ Passed
Next expiry date	2024-12-03
Advice Rear All direction indicators slightly discoloured (4.4.3 (a))	

MOT #7	2023-11-29 11:59	
MOT test number	880339423932	
Result	X Failed	
Fail Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))		
Advice Rear All direction indicators slightly discoloured (4.4.3 (a))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge edges worn , damage to outer sidewall (5.2.3 (e))		
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		

CarCheck.co.uk page 3/12



Advice

Fail

CV66HTU

report date: 2024-03-28

MOT test number

Result

Advice
Offside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice
Rear Brake disc worn, pitted or scored, but not seriously weakened Both discs (1.1.14 (a) (ii))

MOT #5 2021-12-02 17:47 MOT test number 803898316402

Result ✓ Passed

MOT #4 2020-12-04 15:02

MOT test number 480611798938

Result

MOT #3 2020-12-04 10:33

MOT test number 397215080335

Result X Failed

Advice Offside Rear Nail in tyre

Nearside Front Nail in tyre

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2019-10-23 14:48

MOT test number 690841409698

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2019-10-23 11:07

MOT test number 328998110395

Result × Failed

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



✓ MOT

Tax expired: 16 April 2024

Expires: 3 December 2024

Tax status	Expired at 16 April 2024
Days left	14 days too late
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



CV66HTU

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
manage of the same	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12




CV66HTU

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-28
Last registration	2023-11-29
Complete history	See info



Registration #1	2016-10-28	6 mi
Registration #2	2019-10-23	9.060 mi
Registration #3	2019-10-23	9.061 mi
Registration #4	2020-12-04	12.624 mi
Registration #5	2020-12-04	12.624 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 au
Registration #8 Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	***
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30396110

CarCheck.co.uk page 12/12