



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 D SE-L NAV 4WD
Colour	White
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-01
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-01-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	5

MOT #11	2024-01-31 15:49
MOT test number	996697703325
Result	✓ Passed
Next expiry date	2025-01-30

MOT #10	2023-01-26 17:09
MOT test number	262171267051
Result	✓ Passed

MOT #9	2023-01-25 14:58
MOT test number	975745671935
Result	✗ Failed

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #8** 2022-01-14 15:49**MOT test number** 470068107650**Result** ✓ Passed**MOT #7** 2021-01-15 11:26**MOT test number** 416650073277**Result** ✓ Passed**Advice** Nearside Front anti roll bar link plastic lugs broken**Advice** Offside Front anti roll bar link plastic lugs broken**MOT #6** 2021-01-13 16:31**MOT test number** 871701682408**Result** ✗ Failed**Advice** Nearside Front anti roll bar link plastic lugs broken**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Front anti roll bar link plastic lugs broken**MOT #5** 2020-01-06 12:30**MOT test number** 921769708298**Result** ✓ Passed**Advice** Nearside Front Bonnet Damage**Advice** Nearside Front Mirror Case Cracked

**MOT #4** 2018-12-18 13:41**MOT test number** 211579282492**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-01-08 15:46**MOT test number** 610449912695**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside front door mirror loose on its axis**Advice** Oil leak**MOT #2** 2016-12-28 11:10**MOT test number** 987353136038**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2016-01-08 11:23**MOT test number** 550423042762**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
30 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	30 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>ND62LBF</b>
Plate since	2019-09-29
Current registration	<b>ND62LBF</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-10
Last registration	2024-01-31
Complete history	<a href="#">See info</a>



Registration #1	2013-01-10	12 mi
Registration #2	2016-01-08	31.010 mi
Registration #3	2016-12-28	40.182 mi
Registration #4	2018-01-08	46.667 mi
Registration #5	2018-12-18	53.240 mi
Registration #6	2020-01-06	59.573 mi
Registration #7	2021-01-13	63.447 mi
Registration #8	2022-01-01	65.000 mi
Registration #9	2022-01-01	65.000 mi
Registration #10	2022-01-01	65.000 mi
Registration #11	2022-01-01	65.000 mi
Registration #12	2022-01-01	65.000 mi
Registration #13	2024-01-31	65.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30279274