





General information

Make	BMW
Model	530 530D M SPORT
Colour	Green
Year of manufacture	2006
Top speed	154 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	200 g/km
CO2 label	J







Internet history	
Entry 1	
Date	2021-06-20
Pictures	1
Listing price	View report



source: autotrader.co.uk





MOT history

10T expiry date 2024-01-10	
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	36
Total items failed	12

MOT #21	2023-01-11 15:43
MOT test number	527897709110
Result	Passed
Next expiry date	2024-01-10
Minor Nearside Registration plate lamp inoperative in the case of multiple l (b) (i))	lamps or light sources (4.7.1
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, dirt (2.1.3 (g) (i))	but preventing the ingress of
Advice Nearside parking brake Requirements only just met. It would appear requires adjustment or repair	r that the braking system
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Steering rack gaiter damaged or deteriorated, but preventing the ing (g) (i))	gress of dirt both boots (2.1.3

MOT #20		2022-01-10 10:48
MOT test	number	259905487135
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (2))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge and cracked (5.2.3 (e)))



OV56KXJ
report date: 2024-03-29

MOT #19	2021-01-10 13:31
MOT test number	640543681063
Result	✓ Passed
AdviceOil leak, but not excessive (8.4.1 (a) (i))AdviceFront Undertray not fully secure (8.1.1 (b) (i))	

MOT #18	2019-06-25 08:00
MOT test number	860142961098
Result	✓ Passed

MOT #17		2019-06-24 11:53
MOT test	number	798745166005
Result		🗙 Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Tps light on	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
DANGER	OUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #16	2018-06-19 15:25
MOT test number	734024502032
Result	✓ Passed





MOT #15		2018-06-19 10:38
MOT test	number	526623797173
Result		🗙 Failed
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Nearside Front Obligatory mirror does not provide a view to the rear Wing mirro	r (3.3 (c))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))	

MOT #14		2017-06-20 11:37
MOT test	number	665710443826
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit warn inner edge (4.1.E.1)	
Advice	Under trays fitted	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Engine light on	
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)





MOT #13	2017-06-12 10:29	
MOT test number	968000991457	
Result	🗙 Failed	
Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view	(8.1.2a)	
Advice Under trays fitted		
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)		
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)		
Advice Nearside Rear Tyre worn close to the legal limit warn inner edge (4.1.E.1)		
Advice Engine light on		
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)		
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its struct	cture (4.1.D.1b)	
Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)		

MOT #12	2016-06-16 08:55
MOT test number	521994746337
Result	✓ Passed
MOT #11	2015-06-19 10:59
MOT test number	878180475152
Result	✓ Passed
Notice EML LIGHT ON	
Notice Oil leak	





MOT #10		2015-06-18 10:11
MOT test	number	248269365407
Result		🗙 Failed
Fail	Tyre has ply or cords exposed (4.1.D.1b)	
Notice	EML LIGHT ON	
Notice	Oil leak	
MOT #9		2014-05-29 13:11

	2014-05-29 15.11
MOT test number	677589144179
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2014-05-21 16:18
MOT test number	875401744174
Result	🗙 Failed
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Road wheel cracked (4.2.A.1a)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #7	2013-06-11 16:40
MOT test number	108122263131
Result	✓ Passed





MOT #6	2013-06-11 14:49
MOT test number	168672663137
Result	🗙 Failed
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	

MOT #5	2012-06-12 15:24
MOT test number	469954362163
Result	✓ Passed

MOT #4	4	2012-06-11 17:03
MOT te	st number	649723462119
Result		🗙 Failed
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail	Nearside Track rod end ball joint has excessive play (2.2.B.1f)	

MOT #3	2011-05-13 11:53
MOT test number	217833331456
Result	✓ Passed
Notice Nearside rear tyre worn on inner edge	
MOT #2	2010-04-21 15:22
MOT test number	324131110105
Result	✓ Passed

MOT #1	2010-01-29 16:07
MOT test number	394539320099
Result	✓ Passed





Tax & MOT check

X Untaxed	Х МОТ
Tax expired: 31 July 2023	Expired: 10 January 2024
Tax status	Expired at 31 July 2023
Days left	274 days too late
MOT expiry date	10 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F the state	
Category		LAMP
Туре		W.
Damage 2	Law .	PLL
Date	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Category	ANG	
Туре	W	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plate	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-12-20
Last registration	2023-01-11
Complete history	See info



Registration #1	2006-12-20	16 mi
Registration #2	2010-01-29	27.264 mi
Registration #3	2010-04-21	27.664 mi
Registration #4	2011-05-13	48.604 mi
Registration #5	2012-06-11	68.849 mi
Registration #6	2012-06-12	68.849 mi
Registration #7	2013-06-11	88.117 mi
Registration #8	2013-06-11	88.117 mi
Registration #9	2014-05-21	105.307 mi
Registration #10	2014-05-29	105.322 mi
Registration #11	2015-06-18	117.106 mi
Registration #12	2015-06-19	117.106 mi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.227 mi
Registration #20		11.277 est
Registration #21		11.227 mi
Registration #22		11.227 est
Registration #23		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1665 kg
Max. allowed weight	2150 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 15/15