



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 MPI SE
Colour	Silver
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	99 BHP
Max. torque	134 Nm at 3.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-11
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-26
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #8	2024-02-26 10:11
MOT test number	379214227663
Result	✓ Passed
Next expiry date	2025-02-26

MOT #7	2023-02-27 16:39
MOT test number	211995223039
Result	✓ Passed

MOT #6	2022-03-29 12:27
MOT test number	444527778033
Result	✓ Passed

Advice Offside Front tyre perished

Advice Both rear tyres perished

MOT #5	2021-02-24 11:21
MOT test number	897347548452
Result	✓ Passed

**MOT #4** 2020-03-23 15:45**MOT test number** 289992312300**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-03-23 15:02**MOT test number** 799953573672**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer wall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2019-03-11 12:18**MOT test number** 428722799215**Result** ✓ Passed**MOT #1** 2018-01-09 12:19**MOT test number** 889536436213**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-31
Last registration	2024-02-26
Complete history	See info



Registration #1	2015-01-31	12 mi
Registration #2	2018-01-09	4.739 mi
Registration #3	2019-03-11	5.881 mi
Registration #4	2020-03-23	6.549 mi
Registration #5	2020-03-23	6.549 mi
Registration #6	2020-03-23	6.549 mi
Registration #7	2020-03-23	6.549 mi
Registration #8	2020-03-23	6.549 mi
Registration #9	2020-03-23	6.549 mi
Registration #10	2020-03-23	6.549 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1197 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LCEU314379