



General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Grey
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-21
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	23
Total items failed	12

MOT #18 2024-03-26 14:36

MOT test number 442533119109

Result ✓ Passed

Next expiry date 2025-03-29

Advice Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear anti roll bar corroded**Advice** Offside Rear tyre feathering on inside edge**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Outer Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear axle corroded

MOT #17 2023-03-28 14:48

MOT test number 924267230779

Result ✓ Passed**Advice** Surface corrosion present on underside of vehicle

**MOT #16**

2023-03-28 11:05

MOT test number

535425334116

Result

✗ Failed

Advice

Nearside Front All direction indicators slightly discoloured (4.4.3 (a))

Advice

Surface corrosion present on underside of vehicle

Minor

Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Fail

Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Offside Front All direction indicators slightly discoloured (4.4.3 (a))

Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15

2022-03-16 14:26

MOT test number

361094152407

Result

✓ Passed

Advice

Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bush's (5.3.4 (a) (i))

MOT #14

2021-03-30 14:58

MOT test number

355708935575

Result

✓ Passed

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #13

2020-02-20 09:31

MOT test number

178126708695

Result

✓ Passed

**MOT #12** 2019-02-21 12:43**MOT test number** 655767377960**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-03-05 14:29**MOT test number** 394921987660**Result** ✓ Passed**MOT #10** 2018-03-05 11:08**MOT test number** 821387793095**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2017-02-06 12:20**MOT test number** 801971351171**Result** ✓ Passed**MOT #8** 2017-02-06 12:20**MOT test number** 451732924975**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7** 2016-02-04 10:42**MOT test number** 844054401347**Result** ✓ Passed**MOT #6** 2016-02-04 10:42**MOT test number** 947796486530**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam H7 bulb fitted (1.7.5a)**MOT #5** 2015-02-18 13:45**MOT test number** 118049445415**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2015-02-17 16:23**MOT test number** 987788145096**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Space saver wheel fitted N/S/R**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Rear Tyre(s) incorrect because tyres with different aspect ratios are fitted on the same axle.
(4.1.A.1a)**MOT #3** 2013-09-23 13:30**MOT test number** 387816063448**Result** ✓ Passed



MOT #2	2013-09-23 11:44
MOT test number	397436463227
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2012-09-13 11:39
MOT test number	937447352224
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-23
Last registration	2024-03-26
Complete history	See info



Registration #1	2009-09-23	12 mi
Registration #2	2012-09-13	55.315 mi
Registration #3	2013-09-23	73.627 mi
Registration #4	2013-09-23	73.627 mi
Registration #5	2015-02-17	84.817 mi
Registration #6	2015-02-18	84.817 mi
Registration #7	2016-02-04	95.099 mi
Registration #8	2016-02-04	95.099 mi
Registration #9	2017-02-06	108.273 mi
Registration #10	2017-02-06	108.273 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi
Registration #18	2019-05-29	151.377 mi
Registration #19	2019-05-29	151.377 mi
Registration #20	2019-05-29	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425