



report date: 2024-03-28

General information

Make	MAZDA
Model	3 D TS2
Colour	Grey
Year of manufacture	2010
Top speed	114 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-17
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-14
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #13	2023-05-30 15:35
MOT test number	302542332066
Result	✓ Passed
Next expiry date	2024-06-14

MOT #12	2022-06-14 11:20
MOT test number	373947334759
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2021-06-15 16:03
MOT test number	672729332526
Result	✓ Passed

MOT #10	2020-06-05 11:06
MOT test number	954325168807
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9**

2020-06-05 10:18

MOT test number

146324890223

Result**✗ Failed****Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction dash cam fitted (3.1 (a) (ii))**MOT #8**

2019-05-16 11:11

MOT test number

260343251992

Result**✓ Passed****Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))**Advice** Nearside Rear Outer Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #7**

2018-05-14 08:42

MOT test number

366136968987

Result**✓ Passed****Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-03-28 09:00**MOT test number** 498917670045**Result** ✓ Passed**Advice** Engine under shield fitted**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #5** 2016-03-22 12:49**MOT test number** 694756882818**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-03-17 13:58**MOT test number** 496076275082**Result** ✓ Passed**MOT #3** 2015-03-17 11:09**MOT test number** 615366375099**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-03-26 10:56**MOT test number** 115955684435**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-04-05 12:41
MOT test number	397445193065
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
14 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-27
Last registration	2023-05-30
Complete history	See info



Registration #1	2010-03-27	28 mi
Registration #2	2013-04-05	18.019 mi
Registration #3	2014-03-26	22.632 mi
Registration #4	2015-03-17	27.817 mi
Registration #5	2015-03-17	27.817 mi
Registration #6	2016-03-22	33.950 mi
Registration #7	2017-03-28	38.718 mi
Registration #8	2018-05-14	44.437 mi
Registration #9	2019-05-29	50.277 mi
Registration #10	2020-05-29	56.277 mi
Registration #11	2021-05-29	62.277 mi
Registration #12	2022-05-29	68.277 mi
Registration #13	2023-05-30	74.277 mi
Registration #14	2023-05-30	74.277 mi
Registration #15	2023-05-30	74.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1323 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	Y6 313550