





report date: 2024-03-28

### General information

Make	LAND ROVER	
Model	RANGE ROVER VELAR R-DYNAMIC HSE	
Colour	Grey	
Year of manufacture	2019	
Top speed	135 mph	
Gearbox	8 speed automatic	

# Engine & fuel consumption

Power	271 BHP
Max. torque	625 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption combined	38.2 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



### Internet history

### Entry 1

Date 2022-03-12

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-27
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #5		2024-01-26 10:33
MOT test	number	650185536573
Result		✓ Passed
Next expi	y date	2025-01-27
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously	weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



VU68CYL

report date: 2024-03-28

**MOT #4** 2024-01-22 15:17 **MOT** test number 542145950429 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a)) Fail **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3

MOT test number

496636404237

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Registration plate does not conform to the specified requirements (0.1 (d))

 MOT #1
 2022-01-04 11:46

 MOT test number
 822926032745

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	27 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

### Damage 1

Date	
Category	
Tyne	

Damage 2	
Date	
Category	



### Extra LAND ROVER salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many or ROVER have? Check it in the premium report and see all owner registrations. Download to		
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



VU68CYL

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-01-28
Last registration	2024-01-26
Complete history	See info



Registration #1	2019-01-28	21 mi
Registration #2	2022-01-04	13.393 mi
Registration #3		91.777 es
Registration #4	2023-01-16	24.494 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		10.777 au


More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	****
Adult	93%
Children	85%
Pedestrian	74%
Safety systems	72%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2145 mm
Height	1685 mm
Length	4804 mm
Max. allowed weight	2610 kg

# Additional information

Number of seats	5
Number of axles	2
Engine number	1298559306DTA

CarCheck.co.uk page 11/11