





report date: 2024-03-28

### General information

Make	AUDI	
Model	A6 AVANT TDI QUATTRO SE	
Colour	Red	
Year of manufacture	2009	
Top speed	140 mph	
0 - 60 mph	8.4 seconds	
Gearbox	6 speed automatic	

### Engine & fuel consumption

Power	187 BHP	
Max. torque	450 Nm at 1.750 rpm	
Engine capacity	2.698 cc	
Cylinders	6	
Fuel type	Diesel	
Consumption city	30.1 mpg	
Consumption extra urban	48.7 mpg	
Consumption combined	39.8 mpg	
CO2 emission	189 g/km	
CO2 label	J	



CarCheck.co.uk page 1/12



YG59LDN report date: 2024-03-28

MOT history

MOT expiry date	2024-11-03
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #15	2023-11-04 10:17
MOT test number	341064707983
Result	✓ Passed
Next expiry date	2024-11-03
Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #14	2022-10-31 08:23
MOT test number	875478125975
Result	<b>✓</b> Passed
Advice ADVISE SLIGHT DAMAGE ON ALLOYS	

MOT #13		2021-11-02 12:55
MOT test	number	655460794691
Result		✓ Passed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both	sides (1.1.14 (a)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

× Failed

MOT #12 2021-10-22 15:50

**MOT test number** 354564421420

Result

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Upper Suspension arm pin or bush excessively worn Rear arm bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11** 2020-10-19 11:20

MOT test number 283160562270

Result 

Passed

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MOT #10** 2019-10-22 10:10

**MOT test number** 836606973628

CarCheck.co.uk page 3/12



**Advice** 

YG59LDN

report date: 2024-03-28

**MOT** #9 2018-10-03 08:15 737704820415 **MOT** test number Result ✓ Passed **Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Advice (5.3.4 (a) (i))

MOT #8

MOT test number

669297410015

Result

Advice

Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #7
 2016-10-22 08:56

 MOT test number
 447928066510

 Result
 ✓ Passed

MOT #6

MOT test number

Result

Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

MOT #5

MOT test number

178923226862

Result

✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4

MOT test number

Result

Notice Brake pads wearing

MOT #3

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



YG59LDN report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	3 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		
************		
************		
	More info >	
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-27
Last registration	2023-11-04
Complete history	See info



Registration #1	2009-10-27	25 mi
Registration #2	2012-10-30	48.678 mi
Registration #3	2013-11-01	56.955 mi
Registration #4	2014-10-03	63.858 mi
Registration #5	2015-10-28	73.647 mi
Registration #6	2016-10-22	84.663 mi
Registration #7	2016-10-22	84.663 mi
Registration #8	2017-10-21	95.842 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

S0225	Air conditioning
50295	
S0482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4927 mm
Wheel base	2843 mm
Kerb weight	1825 kg
Max. allowed weight	2455 kg

## Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

**Engine number** 

CAN 009162