



General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-11
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	29
Total items failed	7

MOT #132023-10-31 13:05

MOT test number243850933177

Result✓ Passed

Next expiry date2024-11-10

- Advice

Headlamp has a product on the lens but not seriously reducing light output Beam deflectors fitted.
(4.1.4 (b))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources
(4.7.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Towball/hitch not fitted at time of test
- Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Rear Passenger seat(s) missing at time of test

**MOT #12**

2023-10-30 10:37

MOT test number

326406816938

Result**✗ Failed****Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Towball/hitch not fitted at time of test

Fail

Nearside Front Lower Suspension component pin or bush excessively worn Hub lower bush. (5.3.4 (a) (i))

Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice

Headlamp has a product on the lens but not seriously reducing light output Beam deflectors fitted. (4.1.4 (b))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Passenger seat(s) missing at time of test

Fail

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #11

2022-11-11 11:06

MOT test number

669065081991

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Lower Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10**

2022-11-03 09:57

MOT test number

614444393079

Result**✗ Failed**

- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Lower Suspension component pin or bush excessively worn (5.3.4 (a) (i))

MOT #9

2021-11-02 15:05

MOT test number

543552576765

Result**✓ Passed**

- Advice** Rear Passenger seat(s) missing at time of test all folded flat
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides inner / outer faces (1.1.14 (a) (ii))

MOT #8

2020-11-06 14:47

MOT test number

538450194450

Result**✓ Passed**

**MOT #7** 2019-05-25 08:29**MOT test number** 217499124232**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2018-05-26 09:16**MOT test number** 304476261094**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2017-06-06 12:12**MOT test number** 792769275532**Result** ✓ Passed**MOT #4** 2016-05-19 14:35**MOT test number** 256466650422**Result** ✓ Passed**MOT #3** 2015-05-23 10:08**MOT test number** 837083145168**Result** ✓ Passed**MOT #2** 2014-05-29 11:57**MOT test number** 608229544194**Result** ✓ Passed



MOT #1	2013-05-13 15:06
MOT test number	249073933169
Result	✓ Passed
Notice	Nail in nearside rear tyre
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	High level brake light not working.



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-10
Last registration	2023-10-31
Complete history	See info



Registration #1	2010-06-10	16 mi
Registration #2	2013-05-13	27.680 mi
Registration #3	2014-05-29	34.743 mi
Registration #4	2015-05-23	40.332 mi
Registration #5	2016-05-19	49.615 mi
Registration #6	2017-06-06	60.500 mi
Registration #7	2018-05-26	69.516 mi
Registration #8	2019-05-25	76.804 mi
Registration #9	2020-05-25	85.277 mi
Registration #10	2021-05-25	94.277 mi
Registration #11	2022-05-25	103.277 mi
Registration #12	2023-05-25	112.277 mi
Registration #13	2024-05-25	121.277 mi
Registration #14	2025-05-25	130.277 mi
Registration #15	2026-05-25	139.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2238 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWS4031926