



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	HORIZON HDI TEPEE S
Colour	Grey
Year of manufacture	2014
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 3

Date 2023-12-13

Pictures 8




source: g3remarketing.co.uk

Entry 2

Date 2023-02-10

Pictures 25

Listing price [View report](#)





source: cargurus.co.uk

Entry 1

Date 2022-01-19

Pictures 10

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-16
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	20
Total items failed	6

MOT #9	2023-09-04 09:30
MOT test number	914551682087
Result	✓ Passed
Next expiry date	2024-09-16
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #8	2022-09-17 06:49
MOT test number	119395061212
Result	✓ Passed

MOT #7	2022-01-27 16:59
MOT test number	750885350818
Result	✓ Passed

MOT #6	2022-01-20 17:10
MOT test number	167084126883
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Central Exhaust silencer insecure missing (8.1.1 (b) (i))



MOT #5

2021-03-23 16:55

MOT test number

801445729217

Result

✓ Passed

- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Front Power steering component has slight seepage from a component (2.1.5 (a))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

High level stop lamp not working.
- Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #4**

2021-03-23 15:48

MOT test number

523985625294

Result

✗ Failed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** High level stop lamp not working.
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))

MOT #3

2020-02-11 13:02

MOT test number

282250251401

Result

✓ Passed

MOT #2

2018-12-20 14:09

MOT test number

126971213312

Result

✓ Passed

MOT #1

2017-10-02 10:50

MOT test number

215368378621

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	16 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-08-29
Last registration	2023-09-04
Complete history	See info



Registration #1	2014-08-29	16 mi
Registration #2	2017-10-02	13.444 mi
Registration #3	2018-12-20	20.200 mi
Registration #4	2020-02-11	22.611 mi
Registration #5	2021-03-23	26.006 mi
Registration #6	2021-03-23	26.006 mi
Registration #7	2023-09-04	26.006 mi
Registration #8	2023-09-04	26.006 mi
Registration #9	2023-09-04	26.006 mi
Registration #10	2023-09-04	26.006 mi
Registration #11	2023-09-04	26.006 mi
Registration #12	2023-09-04	26.006 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1601 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBEM0319986