





report date: 2024-03-28

General information

Make	MAZDA
Model	cx-3 SPORT NAV PLUS
Colour	Blue
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	119 BHP
Max. torque	206 Nm at 2.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	141 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

entry 1	E	n	tr	ъ	1
---------	---	---	----	---	---

End y 1	
Date	2022-06-04
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



YN68UPZ report date: 2024-03-28

MOT history

MOT expiry date	2024-05-20
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #3		2023-05-06 11:26
MOT test	number	334385547633
Result		✓ Passed
Next expi	ry date	2024-05-20
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2			2023-05-06 11:26
MOT test i	number		717623381466
Result			≍ Failed
Advice	Nearside Rear Ty	re slightly damaged/cracking or perishi	ng (5.2.3 (d) (ii))
Pass wit	h rectification	Offside Rear Rear fog lamp not workin	g (4.5.1 (a) (ii))
Advice	Offside Rear Bra	ce disc worn, pitted or scored, but not s	eriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear N	ail in tyre	
Advice	Offside Front Tyr	e slightly damaged/cracking or perishin	g (5.2.3 (d) (ii))
Advice	Nearside Rear Bi	ake disc worn, pitted or scored, but not	seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-05-21 09:40

MOT test number 366319866497

Result ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion on edges (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion on edges

(1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
HARMAN CO.	

manana and a same a same and a same and a same and a same and a same a same a same and a same and a	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Correct registration	UK SIE
Plate since	
Current registration	IK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-12-21
Last registration	2023-05-06
Complete history	See info



Registration #1	2018-12-21	29 mi
Registration #2	2022-05-21	34.863 mi
Registration #3		11.777 66
Registration #4		77,777 66
Registration #5		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1187 kg
Max. allowed weight	1692 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 50 201968

CarCheck.co.uk page 11/11