



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-09-19
Pictures	6
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-18
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	21
Total items failed	1

MOT #11	2023-07-25 10:58
---------	------------------

MOT test number	271305023089
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-19
------------------	------------

- Advice** Front Brake hose has slight corrosion to ferrule Both corroded (1.1.12 (f) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Both slightly perished (1.1.12 (f) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Inner Steering linkage ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded Both corroded (5.3.1 (b) (i))

**MOT #10**

2023-07-24 14:31

MOT test number

925562853117

Result**✗ Failed**

- Advice** Offside Front Inner Steering linkage ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded Both corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake hose has slight corrosion to ferrule Both corroded (1.1.12 (f) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Both slightly perished (1.1.12 (f) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9

2022-08-11 09:10

MOT test number

897726273906

Result**✓ Passed**

- Advice** Rear Coil spring corroded Both corroded (5.3.1 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Both corroded (1.1.12 (f) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8

2021-08-11 14:00

MOT test number

690229222091

Result**✓ Passed****MOT #7**

2020-08-18 14:54

MOT test number

828634569182

Result**✓ Passed**

**MOT #6** 2019-08-20 11:55**MOT test number** 529765342069**Result** ✓ Passed**MOT #5** 2018-08-14 15:50**MOT test number** 804305366940**Result** ✓ Passed**MOT #4** 2017-08-08 14:18**MOT test number** 347312787466**Result** ✓ Passed**MOT #3** 2016-08-10 13:08**MOT test number** 906012106098**Result** ✓ Passed**MOT #2** 2015-08-11 09:58**MOT test number** 855593893072**Result** ✓ Passed**Advice** O/s rear upper side lamp inoperative**Advice** Front disc pads low**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-08-13 15:00**MOT test number** 365895024442**Result** ✓ Passed**Notice** Osf tyre on 2mm marker



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 August 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-29
Last registration	2023-07-25
Complete history	See info



Registration #1	2011-09-29	18 mi
Registration #2	2014-08-13	86.425 mi
Registration #3	2015-08-11	114.556 mi
Registration #4	2016-08-10	125.250 mi
Registration #5	2017-08-08	131.841 mi
Registration #6	2018-08-14	142.087 mi
Registration #7	2019-08-20	151.617 mi
Registration #8	2020-08-20	161.147 mi
Registration #9	2021-08-20	170.677 mi
Registration #10	2022-08-20	180.207 mi
Registration #11	2023-08-20	189.737 mi
Registration #12	2024-08-20	199.267 mi
Registration #13	2025-08-20	208.797 mi
Registration #14	2026-08-20	218.327 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212