



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA DIAMOND CDTI S/S
Colour	Black
Year of manufacture	2015
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-08
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #8	2023-08-18 09:34
MOT test number	732726914856
Result	✓ Passed
Next expiry date	2024-08-19
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2022-08-11 09:08
MOT test number	919654176457
Result	✓ Passed

MOT #6	2021-08-20 10:33
MOT test number	839471701286
Result	✓ Passed

**MOT #5** 2021-02-04 11:40**MOT test number** 237672959608**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2021-02-04 11:40**MOT test number** 596981779371**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-03-04 10:48**MOT test number** 655745818070**Result** ✓ Passed**MOT #2** 2018-03-07 10:23**MOT test number** 241476568764**Result** ✓ Passed



MOT #1	2018-03-07 09:17
MOT test number	774613932440
Result	✗ Failed
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	EK15OZM
Plate since	2019-06-29
Current registration	EK15OZM
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-31
Last registration	2023-08-18
Complete history	See info



Registration #1	2015-03-31	7 mi
Registration #2	2018-03-07	25.715 mi
Registration #3	2018-03-07	25.715 mi
Registration #4	2019-03-04	31.393 mi
Registration #5	2021-02-04	45.742 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2023-08-18	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2479 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 359171K LNQ