



YD58UCR


report date: 2024-03-29

General information

Make	MAZDA
Model	3 TAKARA
Colour	Red
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	39
Total items failed	4

MOT #19	2023-06-22 10:19
MOT test number	622801535220
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Nearside Rear Brake pad(s) wearing thin and offside (1.1.13 (a) (ii))

MOT #18	2023-06-22 10:19
MOT test number	753431750414
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin and offside (1.1.13 (a) (ii))

MOT #17	2022-06-20 12:23
MOT test number	588431821989
Result	✓ Passed
Advice	Vehicle is Under-sealed.
Advice	Under-chassis, Suspension, Exhaust & Brake components corroded.
Advice	Covers Fitted On Sills (Inner & Outer
Advice	Engine Covers / Under-trays Fitted

**MOT #16**

2022-06-20 12:23

MOT test number

270697285095

Result**✗ Failed****Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Under-chassis, Suspension, Exhaust & Brake components corroded.**Advice** Covers Fitted On Sills (Inner & Outer**Advice** Engine Covers / Under-trays Fitted**Pass with rectification** Offside Front Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Vehicle is Under-sealed.**MOT #15**

2021-04-23 10:47

MOT test number

465462792234

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-04-21 09:09

MOT test number

934852220362

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MOT #13**

2019-12-06 11:01

MOT test number

787473683762

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12**

2019-12-05 10:08

MOT test number

454958589157

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))



MOT #11	2018-12-05 13:34
MOT test number	788631732706
Result	✓ Passed
Advice	Rear suspension running gear showing first signs of corrosion in parts

MOT #10	2018-12-03 11:33
MOT test number	191619594245
Result	✗ Failed
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Rear suspension running gear showing first signs of corrosion in parts
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2017-11-14 17:12
MOT test number	413931372555
Result	✓ Passed

MOT #8	2017-11-14 09:14
MOT test number	746337970811
Result	✗ Failed
Fail	Offside Rear coil spring broken (2.4.C.1a)

MOT #7	2016-11-28 12:00
MOT test number	469460327559
Result	✓ Passed

**MOT #6** 2015-11-25 12:37**MOT test number** 608363810089**Result** ✓ Passed**MOT #5** 2014-12-04 12:20**MOT test number** 755988734310**Result** ✓ Passed**MOT #4** 2014-08-27 16:00**MOT test number** 357789534236**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2013-08-21 14:53**MOT test number** 229933233259**Result** ✓ Passed**MOT #2** 2012-08-21 09:01**MOT test number** 318524232235**Result** ✓ Passed**MOT #1** 2011-08-16 15:57**MOT test number** 796858421242**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YD58UCR
Plate since	2019-03-29
Current registration	YD58UCR
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-03
Last registration	2023-06-22
Complete history	See info



Registration #1	2008-09-03	26 mi
Registration #2	2011-08-16	21.339 mi
Registration #3	2012-08-21	27.730 mi
Registration #4	2013-08-21	34.076 mi
Registration #5	2014-08-27	41.098 mi
Registration #6	2014-12-04	42.179 mi
Registration #7	2015-11-25	49.225 mi
Registration #8	2016-11-28	58.459 mi
Registration #9	2017-11-14	64.520 mi
Registration #10	2017-11-14	64.520 mi
Registration #11	2018-12-03	71.468 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi
Registration #19	2019-06-20	75.377 mi
Registration #20	2019-06-20	75.377 mi
Registration #21	2019-06-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4440 mm
Wheel base	2640 mm
Kerb weight	1290 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 717071