



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	Silver
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
CO2 emission	251 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-06
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-15
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	44
Total items failed	1

MOT #16 2023-07-11 10:37

MOT test number 584387845688

Result ✓ Passed

Next expiry date 2024-07-15

Advice Central Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

Advice Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))

Advice Under trays fitted not allowing full underside inspection

MOT #15 2022-07-14 12:02

MOT test number 254109900093

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush. (5.3.4 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14**

2021-07-16 11:48

MOT test number

468578141662

Result

✓ Passed

- Advice** Exhaust flexi deteriorated
- Advice** Rear row of seats not fitted
- Advice** Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))
- Advice** Handbrake cables rusty
- Advice** Coil spring corroded slight corrosion on both rear springs (5.3.1 (b) (i))

MOT #13

2021-07-15 10:30

MOT test number

607696007500

Result

✗ Failed

- MAJOR** Exhaust has a major leak of exhaust gases rear silencer box (6.1.2 (a))
- Advice** Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))
- Advice** Exhaust flexi deteriorated
- Advice** Rear row of seats not fitted
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt gaiter insecure (2.1.3 (g) (ii))
- Advice** Coil spring corroded slight corrosion on both rear springs (5.3.1 (b) (i))
- Advice** Handbrake cables rusty

**MOT #12**

2020-07-03 13:47

MOT test number

266002357654

Result

✓ Passed

Advice Brake cable damaged but not to excess rusty (1.1.15 (a))**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**Advice** Front exhaust flexi deteriorated**MOT #11**

2020-07-01 08:18

MOT test number

301096446416

Result

✗ Failed

MAJOR Battery insecure and likely to cause a short circuit (4.13 (a) (ii))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Front exhaust flexi deteriorated**Advice** Brake cable damaged but not to excess rusty (1.1.15 (a))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #10**

2019-05-14 10:48

MOT test number

703170492276

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2019-05-09 09:28**MOT test number** 271946179969**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #8** 2018-05-04 15:17**MOT test number** 677723875266**Result** ✓ Passed**Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Steering rack gaiter deteriorated (2.2.D.2d)**MOT #7** 2017-05-02 15:45**MOT test number** 303764217252**Result** ✓ Passed**Advice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-04-22 12:56**MOT test number** 854782313933**Result** ✓ Passed

**MOT #5** 2015-04-21 11:01**MOT test number** 247221315197**Result** ✓ Passed**Notice** Oil leak around and above steering rack ?**Notice** Centre rear seat belt clasp casing missing offside front seat belt clasp casing missing**MOT #4** 2014-04-03 08:48**MOT test number** 669423694038**Result** ✓ Passed**MOT #3** 2014-04-01 15:41**MOT test number** 695281094020**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #2** 2012-04-04 12:43**MOT test number** 307425992096**Result** ✓ Passed**MOT #1** 2011-03-30 11:37**MOT test number** 115569281446**Result** ✓ Passed**Notice** N/s head lamp beam deflector incorrectly fitted**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
15 July 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		15 July 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LS07UXR
Plate since	2019-06-29
Current registration	 LS07UXR
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-06-06
Last registration	2023-07-11
Complete history	See info



Registration #1	2007-06-06	22 mi
Registration #2	2011-03-30	45.758 mi
Registration #3	2012-04-04	53.876 mi
Registration #4	2014-04-01	72.295 mi
Registration #5	2014-04-03	72.295 mi
Registration #6	2015-04-21	85.490 mi
Registration #7	2016-04-22	99.538 mi
Registration #8	2017-05-02	113.046 mi
Registration #9	2019-05-09	137.884 mi
Registration #10	2020-05-09	151.832 mi
Registration #11	2021-05-09	165.780 mi
Registration #12	2022-05-09	179.728 mi
Registration #13	2023-05-09	193.676 mi
Registration #14	2024-05-09	207.624 mi
Registration #15	2025-05-09	221.572 mi
Registration #16	2026-05-09	235.520 mi
Registration #17	2027-05-09	249.468 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2242 mm
Height	2170 mm
Length	4890 mm
Kerb weight	1872 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	BNZ 064338