





### General information

Make	AUDI
Model	TT V6 QUATTRO
Colour	Grey
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.6 seconds
Gearbox	6 speed Semi-Automatic

# Engine & fuel consumption

Power	247 BHP
Max. torque	320 Nm at 2.800 rpm
Engine capacity	3.189 сс
Cylinders	6
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.3 mpg
CO2 emission	238 g/km
CO2 label	L







# Internet history


Entry 1

Date Pictures 2021-06-12

41

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-10-27
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #18	2023-10-26 10:15
MOT test number	247836920890
Result	✓ Passed
Next expiry date	2024-10-27

MOT #17	2022-10-28 10:04
MOT test number	102766003520
Result	✓ Passed

MOT #16		2021-09-17 14:23
MOT test	number	633735565041
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2020-08-03 07:46
MOT test number	765444586131
Result	✓ Passed





MOT #14	2019-08-05 10:17
MOT test number	839491611534
Result	✓ Passed
MOT #13	2018-11-19 11:31
MOT test number	766801243058
Result	✓ Passed
Advice Nearside Front tyre wall slight damage	
MOT #12	2017-11-16 14:40
MOT test number	0702020007
MOT test number	879362036967
Result	879362036967 ✓ Passed
Result	🗸 Passed
Result MOT #11	✓ Passed 2016-10-19 15:13
Result MOT #11 MOT test number	✓ Passed 2016-10-19 15:13 859944414231

MOT #10	2015-10-13 15:21
MOT test number	271653852472
Result	✓ Passed
Advice Engine covers and undertray fitted.	





MOT #9		2014-10-22 10:09
MOT test	number	386495094277
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	

MOT #8	2013-10-21 15:47
MOT test number	708944793270
Result	✓ Passed

MOT #7	2013-10-21 08:55
MOT test number	498724993225
Result	🗙 Failed
Fail         Nearside Stop lamp not working (1.2.1b)	
Notice Offside front beam image no kicked up	
Fail         Offside Stop lamp not working (1.2.1b)	

MOT #6		2012-10-31 12:18
MOT test	number	419585302489
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #5	2012-10-31 11:12
MOT test number	826425402366
Result	🗙 Failed
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Fail         Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2011-10-28 09:06
MOT test number	216041201360
Result	✓ Passed
Notice Rear number plate slightly fadded	

MOT #3	2010-10-12 09:01
MOT test number	282545880235
Result	✓ Passed
MOT #2	2009-10-26 09:22
MOT test number	892409999221
Result	✓ Passed

MOT #1	2008-10-24 09:01
MOT test number	331468498299
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 December 2024 Tax status	Expires: 27 October 2024 Valid until 1 December
Days left	216
MOT expiry date	27 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-11-11
Last registration	2023-10-26
Complete history	<u>See info</u>



2005-11-117 mi2008-10-2433.260 mi2009-10-2643.203 mi2010-10-1251.127 mi2011-10-2859.523 mi2012-10-3169.130 mi2012-10-3169.130 mi2013-10-2174.727 mi2013-10-2174.758 mi
2009-10-2643.203 mi2010-10-1251.127 mi2011-10-2859.523 mi2012-10-3169.130 mi2012-10-3169.130 mi2013-10-2174.727 mi
2010-10-12       51.127 mi         2011-10-28       59.523 mi         2012-10-31       69.130 mi         2012-10-31       69.130 mi         2013-10-21       74.727 mi
2011-10-28       59.523 mi         2012-10-31       69.130 mi         2012-10-31       69.130 mi         2013-10-21       74.727 mi
2012-10-31       69.130 mi         2012-10-31       69.130 mi         2013-10-21       74.727 mi
2012-10-31       69.130 mi         2013-10-21       74.727 mi
2013-10-21 74.727 mi
2013-10-21 74 758 mi
2015 10 21 74.750 111
2014-10-22 82.983 mi
1000-00-00 00.000 au
17775-275-277 87.7777 emi
81175-25-29 81.277 est
8100-20-20 8100-20-20 8100-20-20 8100-20-20 8100-20-20
1000 - 20 - 20 - 20 - 20 - 20 - 20 - 20
1000 - 20 - 20 - 20 - 20 - 20 - 20 - 20
1000         1000 <td< th=""></td<>
1000         1000 <td< th=""></td<>







### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1764 mm
Height	1345 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1590 kg
Max. allowed weight	1890 kg
Additional information	
Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/12

Number of axles	2
Engine number	BHE 012109