



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI XTR
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-07-02
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-02
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	30
Total items failed	5

MOT #18	2023-06-28 11:10
MOT test number	205779082859
Result	✓ Passed
Next expiry date	2024-07-02

MOT #17	2023-06-28 11:10
MOT test number	987825405053
Result	✗ Failed
<b>Pass with rectification</b> Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	

MOT #16	2022-06-27 10:10
MOT test number	178700164668
Result	✓ Passed

MOT #15	2021-07-03 12:43
MOT test number	473350088266
Result	✓ Passed

**MOT #14**

2021-06-11 14:01

**MOT test number**

984984481384

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust heat shield insecure
- Advice** Offside Rear Tyre slightly damaged Distorted on tread face inner edge (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-11-06 15:03

**MOT test number**

655300873227

**Result**

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Tyre obviously under inflated (5.2.3 (l))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre slightly damaged distorted on tread face inner edge (5.2.3 (d) (ii))
- Advice** Exhaust heat-shield insecure

**MOT #12**

2019-05-23 14:11

**MOT test number**

473571303353

**Result**

✓ Passed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Rear exhaust heat-shield insecure**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2019-05-23 09:25

**MOT test number**

146479879498

**Result**

✗ Failed

**Fail** Offside Front Position lamp not working (4.2.1 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Rear exhaust heat-shield insecure**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10**

2018-06-14 11:57

**MOT test number**

690934957512

**Result**

✓ Passed

**Advice** Offside Rear Nail in tyre**Advice** Rear exhaust heatshield loose**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2017-06-08 09:58**MOT test number** 898705933295**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #8** 2016-06-15 10:05**MOT test number** 394102370007**Result** ✓ Passed**MOT #7** 2016-06-15 10:05**MOT test number** 997737362052**Result** ✗ Failed**Pass with rectification** Nearside Front Brake pad(s) modified and seriously weakened (3.5.1n)**MOT #6** 2015-06-16 14:11**MOT test number** 296147265149**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-06-15 15:56**MOT test number** 308576265192**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Centre Rear Statutory seat belt missing (5.1.1)



MOT #4	2014-03-07 13:40
MOT test number	307516964052
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2013-03-01 10:41
MOT test number	988100163084
Result	✓ Passed

MOT #2	2012-02-29 12:53
MOT test number	885240062056
Result	✓ Passed

MOT #1	2010-09-13 15:16
MOT test number	790686550202
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
2 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	2 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-12
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2007-03-12	12 mi
Registration #2	2010-09-13	16.823 mi
Registration #3	2012-02-29	27.721 mi
Registration #4	2013-03-01	35.649 mi
Registration #5	2014-03-07	43.691 mi
Registration #6	2015-06-15	46.211 mi
Registration #7	2015-06-16	46.232 mi
Registration #8	2016-06-15	50.271 mi
Registration #9	2016-06-15	50.271 mi
Registration #10	2017-06-08	53.244 mi
Registration #11	2019-06-28	55.277 mi
Registration #12	2019-06-28	55.277 mi
Registration #13	2019-06-28	55.277 mi
Registration #14	2019-06-28	55.277 mi
Registration #15	2019-06-28	55.277 mi
Registration #16	2019-06-28	55.277 mi
Registration #17	2019-06-28	55.277 mi
Registration #18	2019-06-28	55.277 mi
Registration #19	2019-06-28	55.277 mi
Registration #20	2019-06-28	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	1AZ5678590
---------------	------------