





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Red
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

## Entry 2

Date 2022-01-01

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1


Date	2021-12-31
------	------------


Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2025-01-22
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	34
Total items failed	3

MOT #12		2024-01-23 16:04
MOT test	number	335177688697
Result		✓ Passed
Next expi	y date	2025-01-22
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.3	1.11 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.3	11 (c))

MOT #11		2024-01-19 12:18
MOT test	number	745905327840
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
<b>Fail</b> N	earside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	L (c))

CarCheck.co.uk page 3/12



Advice

YR62UGP

report date: 2024-03-29

MOT test number

778303986096

Result

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #9
 2021-12-29 14:42

 MOT test number
 318812748190

 Result
 ✓ Passed

 MOT #8
 2021-01-04 11:48

 MOT test number
 243936562116

 Passed
 243936562116

MOT test number

Result

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Road wheel slightly distorted both front (5.2.2 (c) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

**MOT #7** 2019-12-09 11:47 **MOT** test number 697703851266 Result ✓ Passed **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened O/S and N/S (1.1.14 (a) (ii)) Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Suspension arm pin or bush worn but not resulting in excessive movement O/S and N/S Advice (5.3.4 (a) (i)) **Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #6** 2019-12-09 11:47 **MOT** test number 294039256895 Result **X** Failed Front Brake disc worn, pitted or scored, but not seriously weakened O/S and N/S (1.1.14 (a) (ii)) Advice **Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Front Suspension arm pin or bush worn but not resulting in excessive movement O/S and N/S (5.3.4 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i)) Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Advice

MOT #5	2018-12-28 13:22
MOT test number	844430214363
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #4

MOT test number

Result

Advice Items removed from driver's view prior to test

2017-11-20 11:37

175089501747

✓ Passed

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

# Owner history

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		GEOT
***********		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-26
Last registration	2024-01-23
Complete history	See info



Registration #1	2012-09-26	8 mi
Registration #2	2015-09-21	27.030 mi
Registration #3	2016-11-22	35.830 mi
Registration #4	2016-11-22	35.830 mi
Registration #5	2017-11-20	44.627 mi
Registration #6	2018-12-28	52.394 mi
Registration #7	2019-12-09	57.168 mi
Registration #8	2019-12-09	57.168 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 12/12