



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC TDCI 140
Colour	Silver
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #8	2021-05-20 14:09
MOT test number	951629924773
Result	✓ Passed
Next expiry date	2022-05-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2020-07-10 16:00
MOT test number	989709212175
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #6	2020-07-08 16:25
MOT test number	886300487835
Result	✗ Failed
MAJOR	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Fuel cap/sealing device ineffective (6.1.3 (b) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #5** 2019-07-09 16:02**MOT test number** 369563535803**Result** ✓ Passed**Advice** Crosion under neath**MOT #4** 2015-05-15 17:48**MOT test number** 567675635130**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2015-05-15 12:00**MOT test number** 566715535102**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Macpherson strut worn but not seriously weakened (2.4.G.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2014-05-09 09:47**MOT test number** 416769524163**Result** ✓ Passed**MOT #1** 2013-03-02 09:52**MOT test number** 218781663044**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2010-03-26
Last registration	2021-05-20
Complete history	See info



Registration #1	2010-03-26	9 mi
Registration #2	2013-03-02	55.450 mi
Registration #3	2014-05-09	71.434 mi
Registration #4	2015-05-15	83.345 mi
Registration #5	2015-05-15	83.345 mi
Registration #6	2015-05-15	83.345 mi
Registration #7	2015-05-15	83.345 mi
Registration #8	2015-05-15	83.345 mi
Registration #9	2015-05-15	83.345 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1483 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL33474