



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J








Internet history

Entry 1

Date	2021-06-16
Pictures	72
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-15
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	8

MOT #14	2023-08-01 07:52
MOT test number	252220733433
Result	✓ Passed
Next expiry date	2024-08-15

MOT #13	2023-07-25 08:16
MOT test number	290409762001
Result	✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12	2022-08-09 13:36
MOT test number	356000953007
Result	✓ Passed

**MOT #11** 2022-08-08 09:24**MOT test number** 113773075459**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10** 2021-08-16 15:40**MOT test number** 272208121968**Result** ✓ Passed**MOT #9** 2020-06-15 12:02**MOT test number** 429455415399**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2019-06-06 14:57**MOT test number** 812744847720**Result** ✓ Passed**Advice** All Four Tyres Perishing Between The Treads.**MOT #7** 2018-06-04 12:55**MOT test number** 341534174503**Result** ✓ Passed**Advice** Coil spring corroded Both rear springs (5.3.1 (b) (i))**Advice** Tyre slightly damaged/cracking or perishing All tires in tread pattern (5.2.3 (d) (i))

**MOT #6**

2018-06-04 10:14

MOT test number

870593791045

Result

✗ Failed

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Tyre slightly damaged/cracking or perishing All tires in tread pattern (5.2.3 (d) (i))**Fail** Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen no beam pattern!! (4.1.2 (a))**Advice** Coil spring corroded Both rear springs (5.3.1 (b) (i))**MOT #5**

2017-06-12 10:08

MOT test number

288036747265

Result

✓ Passed

Advice Oil misting from engine**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm front bush (2.4.G.2)**Advice** Nearside Rear tyre perishing on sidewall and between tread**Advice** Stone chip on front screen**Advice** Oil misting from gearbox area**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm front bush (2.4.G.2)**Advice** Offside Rear tyre perishing on sidewall and between tread**MOT #4**

2016-06-09 08:50

MOT test number

426466280884

Result

✓ Passed

MOT #3

2015-06-11 10:03

MOT test number

405812565170

Result

✓ Passed



MOT #2	2014-06-17 10:13
MOT test number	159018664174
Result	✓ Passed
<div>Notice</div> Offside And Nearside Rear Tyres Starting To Break Up Between The Treads.	

MOT #1	2013-07-01 11:53
MOT test number	526452883144
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-02
Last registration	2023-08-01
Complete history	See info



Registration #1	2010-07-02	17 mi
Registration #2	2013-07-01	22.466 mi
Registration #3	2014-06-17	34.324 mi
Registration #4	2015-06-11	46.953 mi
Registration #5	2016-06-09	59.146 mi
Registration #6	2017-06-12	69.293 mi
Registration #7	2018-06-04	77.534 mi
Registration #8	2018-06-04	77.534 mi
Registration #9	2019-06-04	85.775 mi
Registration #10	2019-06-04	94.016 mi
Registration #11	2019-06-04	102.257 mi
Registration #12	2019-06-04	110.498 mi
Registration #13	2019-06-04	118.739 mi
Registration #14	2019-06-04	126.980 mi
Registration #15	2019-06-04	135.221 mi
Registration #16	2019-06-04	143.462 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBAH003807