



HYUNDAI



report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Black
Year of manufacture	2014
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-05-24
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	9

MOT #9	2023-06-14 09:26
MOT test number	955695589229
Result	✓ Passed
Next expiry date	2024-06-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-06-20 09:06
MOT test number	311601986047
Result	✓ Passed

MOT #7	2021-06-21 10:46
MOT test number	550762734487
Result	✓ Passed

MOT #6	2020-07-24 12:28
MOT test number	321899583527
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #5**

2020-07-20 12:33

**MOT test number**

886763798295

**Result****✗ Failed****Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded from flexi (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Brake pipe excessively corroded from flexi (1.1.11 (c))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #4**

2019-03-28 14:39

**MOT test number**

613478395497

**Result****✓ Passed****MOT #3**

2019-03-26 12:05

**MOT test number**

288353604513

**Result****✗ Failed****Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))



MOT #2	2018-03-19 16:37
MOT test number	916914621377
Result	✓ Passed

MOT #1	2017-12-22 14:15
MOT test number	534051493624
Result	✓ Passed

- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Tyre worn close to the legal limit 2mm tyre is also wearing off on the outer edge and smooth on the inner edge (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin pads cant be measured but look low (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>NA64EWJ</b>
Plate since	2019-09-28
Current registration	<b>NA64EWJ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-11-07
Last registration	2023-06-14
Complete history	<a href="#">See info</a>



Registration #1	2014-11-07	16 mi
Registration #2	2017-12-22	26.423 mi
Registration #3	2018-03-19	27.279 mi
Registration #4	2019-03-26	32.904 mi
Registration #5	2019-03-28	32.905 mi
Registration #6	2020-07-20	38.599 mi
Registration #7	2020-09-20	39.277 mi
Registration #8	2020-09-20	39.277 mi
Registration #9	2020-09-20	39.277 mi
Registration #10	2020-09-20	39.277 mi
Registration #11	2020-09-20	39.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCEZ336660