



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 30 L1H1 100 SWB PV
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-22
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-08-31
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	7

MOT #15 2023-09-01 07:37**MOT test number** 809057778795**Result** ✓ Passed**Next expiry date** 2024-08-31**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced both inner and outer sills (6.1.1 (c) (i))**Advice** Play in steering rack inner joint(s)**MOT #14** 2021-03-19 10:33**MOT test number** 161104326062**Result** ✓ Passed**Advice** Front Shock absorbers light misting of oil or has limited damping effect both side (5.3.2 (b))**Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))**Advice** Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13** 2020-03-20 11:19**MOT test number** 473603810194**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2019-03-25 13:59**MOT test number** 851366847747**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2019-03-25 13:59**MOT test number** 328930505425**Result** ✗ Failed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #10** 2018-04-05 13:01**MOT test number** 293436406018**Result** ✓ Passed

**MOT #9** 2018-04-05 13:01**MOT test number** 684298319378**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2017-04-11 11:43**MOT test number** 324537094612**Result** ✓ Passed**MOT #7** 2016-04-18 16:30**MOT test number** 315362667072**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-04-18 09:37**MOT test number** 736859928445**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear rear brake binding (3.7.B.1)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #5** 2015-04-09 12:01**MOT test number** 947929895024**Result** ✓ Passed



MOT #4	2014-04-01 12:02
---------------	------------------

MOT test number	609741694093
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

MOT #3	2013-04-04 11:48
---------------	------------------

MOT test number	128864593457
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-03-21 15:19
---------------	------------------

MOT test number	799531482020
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2011-04-06 11:54
---------------	------------------

MOT test number	328636191010
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 November
-------------------	------------------------

Days left	185
------------------	-----

MOT expiry date	31 August 2024
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-04-18
Last registration	2023-09-01
Complete history	See info



Registration #1	2008-04-18	16 mi
Registration #2	2011-04-06	41.862 mi
Registration #3	2012-03-21	50.811 mi
Registration #4	2013-04-04	59.176 mi
Registration #5	2014-04-01	71.596 mi
Registration #6	2015-04-09	84.434 mi
Registration #7	2016-04-18	95.471 mi
Registration #8	2016-04-18	95.471 mi
Registration #9	2017-04-11	107.158 mi
Registration #10	2018-04-11	118.845 mi
Registration #11	2019-04-11	130.532 mi
Registration #12	2020-04-11	142.219 mi
Registration #13	2021-04-11	153.906 mi
Registration #14	2022-04-11	165.593 mi
Registration #15	2023-04-11	177.280 mi
Registration #16	2024-04-11	188.967 mi
Registration #17	2025-04-11	200.654 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2254 mm
Length	4963 mm
Kerb weight	1845 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ10242931