



**KB54KGX**

report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Silver
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg



**MOT history**

<b>MOT #17</b>	2020-09-16 14:41
<b>MOT test number</b>	367371935806
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-09-15

<b>MOT #16</b>	2019-08-06 14:11
<b>MOT test number</b>	590857330473
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2018-08-24 15:23
<b>MOT test number</b>	243764911933
<b>Result</b>	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #14</b>	2017-08-22 15:08
<b>MOT test number</b>	580253797545
<b>Result</b>	✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front drive shaft support bearing slightly worn (2.5.C.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #13</b>	2016-08-20 09:27
<b>MOT test number</b>	898315656858
<b>Result</b>	✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12

2015-08-15 10:44

MOT test number

576197925272

Result		✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Front Brake lining(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Rear tyres starting to show signs of perishing 195/60/15	

**MOT #11** 2015-08-15 10:22**MOT test number** 325187925253**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear tyres starting to show signs of perishing 195/60/15**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)**MOT #10** 2014-08-23 12:21**MOT test number** 197755534260**Result** ✓ Passed**Notice** Nearside front tyre worn on outer edge**MOT #9** 2014-08-23 09:48**MOT test number** 219165934277**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Notice** Nearside front tyre worn on outer edge

**MOT #8** 2013-08-13 16:21**MOT test number** 855835623214**Result** ✓ Passed**MOT #7** 2013-08-13 16:21**MOT test number** 249835623213**Result** ✗ Failed

- Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Centre Rear Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #6** 2012-07-27 15:24**MOT test number** 696919402217**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear exhaust brackets corroded

**MOT #5** 2011-07-29 09:49**MOT test number** 928140111272**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Exhaust back box brackets corroded

**MOT #4**

2010-07-30 15:38

**MOT test number**

493411110288

**Result**

✓ Passed

- Notice** MIRROR HANGER REMOVE
- Notice** SLIGHT WEAR TO FRONT BRAKE DISCS
- Notice** HEAVY CORROSSION TO REAR EXHAUST BRACKET
- Notice** SLIGHT WEAR TO O/S FRONT WHEEL BEARING

**MOT #3**

2010-07-30 10:27

**MOT test number**

803651410299

**Result**

✗ Failed

- Notice** MIRROR HANGER REMOVE
- Fail** Nearside Headlamp aim too low (1.8)
- Notice** SLIGHT WEAR TO FRONT BRAKE DISCS
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Notice** ADVISE OIL LEVEL LOW
- Notice** HEAVY CORROSSION TO REAR EXHAUST BRACKET
- Fail** Offside Headlamp aim too low (1.8)
- Notice** SLIGHT WEAR TO O/S FRONT WHEEL BEARING



MOT #2	2009-08-25 15:35
MOT test number	663127839214
Result	✓ Passed
Notice	Small chip in windscreen
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Tyre size 195 60 15 T

MOT #1	2008-07-28 16:03
MOT test number	822880918273
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>KB54KGX</b>
Plate since	2024-03-28
Current registration	<b>KB54KGX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-02-18
Last registration	2020-09-16
Complete history	<a href="#">See info</a>



Registration #1	2005-02-18	21 mi
Registration #2	2008-07-28	29.565 mi
Registration #3	2009-08-25	37.056 mi
Registration #4	2010-07-30	42.239 mi
Registration #5	2010-07-30	42.239 mi
Registration #6	2011-07-29	47.050 mi
Registration #7	2012-07-27	51.969 mi
Registration #8	2013-08-13	57.607 mi
Registration #9	2014-08-23	64.172 mi
Registration #10	2015-08-23	71.377 mi
Registration #11	2016-08-23	78.582 mi
Registration #12	2017-08-23	85.787 mi
Registration #13	2018-08-23	92.992 mi
Registration #14	2019-08-23	100.197 mi
Registration #15	2020-09-16	107.402 mi
Registration #16	2021-09-16	114.607 mi
Registration #17	2022-09-16	121.812 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1082 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	5J13755
---------------	---------