



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B200 CDI SE
Colour	Black
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	9.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	138 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	62
Total items failed	5

MOT #22	2024-03-02 08:55
MOT test number	334450113499
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Coil spring corroded Both (5.3.1 (b) (i))



MOT #21

2024-02-28 12:27

MOT test number

270173366843

Result

✗ Failed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Nearside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Coil spring corroded Both (5.3.1 (b) (i))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #20**

2024-01-12 15:02

MOT test number

448804505251

Result**✗ Failed**

- MAJOR** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn front bushes (5.3.4 (a) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Play in steering rack inner joint(s) nearside and offside
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

MOT #19

2023-01-11 12:50

MOT test number

205427021108

Result**✓ Passed**

- Advice** Offside Rear Brake pad friction material separated from back plate

MOT #18

2023-01-09 10:44

MOT test number

765001027806

Result**✗ Failed**

- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Brake pad friction material separated from back plate
- MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #17** 2022-01-08 09:53**MOT test number** 785237754712**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**MOT #16** 2020-12-30 14:01**MOT test number** 371451440124**Result** ✓ Passed**MOT #15** 2020-12-30 14:01**MOT test number** 222510347208**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour bulb (4.4.3 (a))**MOT #14** 2020-01-07 13:48**MOT test number** 221051910311**Result** ✓ Passed**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #13**

2020-01-02 11:25

MOT test number

805110216862

Result**✗ Failed****DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MAJOR** Nearside Body component damaged and likely to cause injury side repeater lens damaged (6.2.1 (a) (i))**Advice** Nearside parking brake grabs**DANGEROUS** Nearside Rear Road wheel fractured (5.2.2 (a))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Road wheel slightly distorted (5.2.2 (c) (i))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #12**

2019-01-08 13:06

MOT test number

416604048829

Result**✓ Passed****MOT #11**

2019-01-08 13:06

MOT test number

205353796910

Result**✗ Failed****Pass with rectification** Shock absorbers has a serious fluid leak both front (5.3.2 (b))

**MOT #10** 2018-03-17 15:15**MOT test number** 973045930806**Result** ✓ Passed**MOT #9** 2018-03-17 15:15**MOT test number** 700663146700**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #8** 2017-03-20 16:20**MOT test number** 493170468224**Result** ✓ Passed**MOT #7** 2016-02-19 12:29**MOT test number** 340720666778**Result** ✓ Passed**MOT #6** 2015-02-23 10:17**MOT test number** 426314055011**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Rear tyres perrished**Notice** Brake pads appear low**Notice** Front tyres worn on inner edge

**MOT #5**

2014-02-22 13:07

MOT test number

319803754000

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4

2013-03-05 11:18

MOT test number

199644363401

Result

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Child seat fitted to left rear passenger seat not allowing full inspection of adult belt.

MOT #3

2012-03-06 09:09

MOT test number

999796662090

Result

✓ Passed

- Notice** Unable to inspect all brake and fuel lines due to under vehicle covers



MOT #2	2012-03-06 09:09
MOT test number	458936462094
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Unable to inspect all brake and fuel lines due to under vehicle covers

MOT #1	2011-05-13 09:58
MOT test number	276433931402
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-03-17
Last registration	2024-03-02
Complete history	See info



Registration #1	2008-03-17	23 mi
Registration #2	2011-05-13	25.036 mi
Registration #3	2012-03-06	27.546 mi
Registration #4	2013-03-05	37.150 mi
Registration #5	2014-02-22	46.614 mi
Registration #6	2015-02-23	56.893 mi
Registration #7	2016-02-19	66.332 mi
Registration #8	2017-03-20	75.585 mi
Registration #9	2018-03-17	84.778 mi
Registration #10	2018-03-17	84.778 mi
Registration #11	2019-01-08	93.094 mi
Registration #12	2019-01-08	93.094 mi
Registration #13	2019-01-08	93.094 mi
Registration #14	2019-01-08	93.094 mi
Registration #15	2019-01-08	93.094 mi
Registration #16	2019-01-08	93.094 mi
Registration #17	2019-01-08	93.094 mi
Registration #18	2019-01-08	93.094 mi
Registration #19	2019-01-08	93.094 mi
Registration #20	2019-01-08	93.094 mi
Registration #21	2019-01-08	93.094 mi
Registration #22	2019-01-08	93.094 mi
Registration #23	2019-01-08	93.094 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094130438047