



**KNI4UEH**

report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D4 SE
Colour	Grey
Year of manufacture	2014
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2


Date	2022-02-12
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-02-12
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	28
Total items failed	0

MOT #10 2024-02-22 11:10

MOT test number 493116856380

Result ✓ Passed

Next expiry date 2025-02-23

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Bold inside edge. (5.2.3 (e))

MOT #9 2024-02-22 10:36

MOT test number 653572339030

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Bold inside edge. (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- MAJOR** Nearside Front Outline marker lamp not working (4.2.1 (a) (ii))

MOT #8 2023-02-24 08:05

MOT test number 482725267706

Result ✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2022-03-17 14:25**MOT test number** 593512343762**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #6** 2022-03-16 16:50**MOT test number** 711841010517**Result** ✗ Failed**DANGEROUS** Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**DANGEROUS** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2021-03-05 16:18**MOT test number** 491879933111**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted slight buckle on inner rim (5.2.2 (c) (i))**Advice** Both rear tyres are wearing on inner shoulders**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm to body bush is perishing (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-03-16 12:41**MOT test number** 390344206313**Result** ✓ Passed**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #3** 2019-03-04 12:48**MOT test number** 655295503110**Result** ✓ Passed**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #2** 2018-03-12 11:07**MOT test number** 245101160176**Result** ✓ Passed**Advice** Nearside Rear tyre is wearing very heavily on the inner shoulder**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened slightly worn and lipped (3.5.1i)**Advice** Nearside Rear tyre tread wearing low**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre is wearing heavily on the inner shoulder**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened slightly worn and lipped (3.5.1i)**Advice** Offside Rear tyre tread wearing low**MOT #1** 2017-03-15 14:11**MOT test number** 650506496090**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>KN14UEH</b>
Plate since	2019-03-29
Current registration	<b>KN14UEH</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-26
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2014-03-26	6 mi
Registration #2	2017-03-15	56.227 mi
Registration #3	2018-03-12	66.103 mi
Registration #4	2019-03-04	75.560 mi
Registration #5	2020-03-16	88.517 mi
Registration #6	2021-03-05	93.907 mi
Registration #7	2022-03-22	95.277 mi
Registration #8	2023-03-22	95.277 mi
Registration #9	2023-03-22	95.277 mi
Registration #10	2023-03-22	95.277 mi
Registration #11	2023-03-22	95.277 mi
Registration #12	2023-03-22	95.277 mi
Registration #13	2024-02-22	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1758 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1066143