





report date: 2024-03-29

### General information

Make	MINI
Model	COOPER D ONE D
Colour	White
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-11-05

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# **MOT** history

MOT expiry date	2024-08-09
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #10	2023-08-09 11:26
MOT test number	176303782450
Result	✓ Passed
Next expiry date	2024-08-09

MOT #9	2022-08-03 13:10
MOT test number	758505716758
Result	<b>✓</b> Passed

MOT #8	2021-07-26 11:26
MOT test number	695775616347
Result	✓ Passed

**Advice** Central Front Upper Items removed from driver's view prior to test (air freshener removed from interior mirror)

Advice Central Rear Lower Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7	2021-07-26 09:48
MOT test number	460516377113
Result	<b>×</b> Failed
Fail (ii) Offside Front Windscreen wiper does not clear the windscreen effectivel	ly (blade rubber split) (3.4 (b)
Advice Central Rear Lower Registration plate deteriorated but not likely to b	pe misread (0.1 (b))
Advice Central Front Upper Items removed from driver's view prior to test (a interior mirror)	air freshener removed from

CarCheck.co.uk page 3/12



**Advice** 

FG13DLF

report date: 2024-03-29

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5

MOT test number

148995656067

Result

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #4
 2018-06-09 08:07

 MOT test number
 390065009088

 Result
 ✓ Passed

 MOT #3
 2017-06-22 12:01

 MOT test number
 229807681647

 Result
 ✓ Passed

MOT #2 2017-06-22 12:01

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT test number 704533357890

Result × Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/12



MOT #1 2016-07-26 15:53

**MOT test number** 682656571772

**Result** ✓ Passed

Advice

Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

e when misterly	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
*********	
*************	
manage of the same	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-07-29
Last registration	2023-08-09
Complete history	See info



Registration #1	2013-07-29	6 mi
Registration #2	2016-07-26	36.907 mi
Registration #3	2017-06-22	47.752 mi
Registration #4	2017-06-22	47.752 mi
Registration #5	2018-06-09	52.298 mi
Registration #6	2019-06-01	56.862 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11 .117 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

**Engine number** 70728575