



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK270 CDI ELEGANCE
Colour	Blue
Year of manufacture	2004
Top speed	143 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.685 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-08-06
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-07-12
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-03-28
-----------------	------------

MOT pass rate	83 %
---------------	------

MOT passed	15
------------	----

Failed MOT tests	3
------------------	---

Total advice items	29
--------------------	----

Total items failed	6
--------------------	---

MOT #18	2021-03-17 10:36
---------	------------------

MOT test number	143477829430
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-03-28
------------------	------------

Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
--------	---

Advice	Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
--------	---

Advice	Front and rear suspension has surface corrosion
--------	---

Advice	Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
--------	--

Advice	Under body has surface corrosion
--------	----------------------------------

MOT #17	2020-03-09 13:54
---------	------------------

MOT test number	552999254150
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Nearside headlamp deteriorating
--------	---------------------------------

Advice	Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))
--------	---

**MOT #16** 2020-03-09 11:41**MOT test number** 695908291043**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside headlamp deteriorating**Advice** Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))**MOT #15** 2019-03-05 09:59**MOT test number** 478180258766**Result** ✓ Passed**MOT #14** 2018-03-28 09:23**MOT test number** 504276796682**Result** ✓ Passed**MOT #13** 2017-03-29 15:14**MOT test number** 568836838041**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)**MOT #12** 2016-03-24 10:02**MOT test number** 482014412037**Result** ✓ Passed

**MOT #11**

2015-03-25 09:49

MOT test number

486764685071

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Corrosion to the exhaust rear box**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2014-03-27 08:39

MOT test number

427496384027

Result

✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Notice** Rear exhaust box corroded and deteriorated.**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2014-03-21 08:55

MOT test number

269720784090

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Rear brake binding (3.7.B.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Rear exhaust box corroded and deteriorated.
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front coil spring fractured (2.4.C.1a)
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

MOT #8

2013-03-22 11:06

MOT test number

987731083097

Result**✓ Passed**

- Notice** Slight corrosion on front brake discs..
- Notice** Rear exhaust deteriorated.
- Notice** Rear brake pads worn.

MOT #7

2013-03-15 15:05

MOT test number

517004873070

Result**✗ Failed**

- Notice** Rear exhaust deteriorated.
- Notice** Rear brake pads worn.
- Fail** Offside Front coil spring fractured (2.4.C.1a)
- Notice** Slight corrosion on front brake discs..



MOT #6	2012-02-22 16:04
MOT test number	778093352093
Result	✓ Passed
MOT #5	2011-03-04 12:04
MOT test number	157703861459
Result	✓ Passed
MOT #4	2010-02-09 15:13
MOT test number	331230540014
Result	✓ Passed
MOT #3	2009-02-18 09:40
MOT test number	153489349037
Result	✓ Passed
MOT #2	2008-02-18 09:34
MOT test number	154549348045
Result	✓ Passed
MOT #1	2007-03-01 15:28
MOT test number	404130567079
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 September 2021

X

MOT

Expired:
28 March 2022

Tax status	Expired at 30 September
Days left	942 days too late
MOT expiry date	28 March 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 AD53LWY
Plate since	2024-03-29
Current registration	 AD53LWY
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-02-20
Last registration	2021-03-17
Complete history	See info



Registration #1	2004-02-20	12 mi
Registration #2	2007-03-01	37.760 mi
Registration #3	2008-02-18	43.162 mi
Registration #4	2009-02-18	47.321 mi
Registration #5	2010-02-09	51.312 mi
Registration #6	2011-03-04	60.635 mi
Registration #7	2012-02-22	68.488 mi
Registration #8	2013-03-15	76.945 mi
Registration #9	2013-03-22	77.011 mi
Registration #10	2014-03-21	81.934 mi
Registration #11	2014-03-27	81.942 mi
Registration #12	2015-03-20	81.942 mi
Registration #13	2016-03-20	81.942 mi
Registration #14	2017-03-20	81.942 mi
Registration #15	2018-03-20	81.942 mi
Registration #16	2019-03-20	81.942 mi
Registration #17	2020-03-20	81.942 mi
Registration #18	2021-03-20	81.942 mi
Registration #19	2022-03-20	81.942 mi
Registration #20	2023-03-20	81.942 mi
Registration #21	2024-03-20	81.942 mi

More info >



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4638 mm
Wheel base	2715 mm
Kerb weight	1645 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	61296730345073