



PEUGEOT



MKI7TGU

report date: 2024-03-28

General information

Make	PEUGEOT
Model	308 BLUE HDI S/S SW ALLURE
Colour	Blue
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	299 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	78.5 mpg
Consumption extra urban	88.3 mpg
Consumption combined	85.6 mpg
CO2 emission	85 g/km
CO2 label	A







Internet history

Entry 2


Date	2021-07-24
Pictures	29
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-07-22
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-08
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	18
Total items failed	14

MOT #9	2024-04-04 08:45
MOT test number	108120916208
Result	✓ Passed
Next expiry date	2025-04-08
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #8	2024-04-04 08:45
MOT test number	542427256300
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))

MOT #7	2023-03-21 16:44
MOT test number	195012867656
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #6** 2023-03-20 12:16**MOT test number** 963205554331**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Tyre pressure light on**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #5** 2022-04-05 09:49**MOT test number** 164430913135**Result** ✓ Passed**MOT #4** 2021-04-09 15:56**MOT test number** 573765580868**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall as marked (5.2.3 (d) (i))**MOT #3** 2021-04-09 11:33**MOT test number** 342405518192**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps not working (4.7.1 (b) (ii))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Offside Rear Tyre pressure monitoring system malfunctioning or obviously inoperative pressure low also nail in tyre (5.2.3 (h))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall as marked (5.2.3 (d) (i))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Offside Headlamp insecure (4.1.1 (c))



<b>MOT #2</b>	2020-03-03 12:10
<b>MOT test number</b>	675399578553
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2020-03-02 11:09
<b>MOT test number</b>	348506391416
<b>Result</b>	✗ Failed

- Fail** Offside Rear Road wheel fixing missing 1 bolt missing (5.2.1 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))
- Advice** Offside Front Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Urea warning light illuminated on dash
- Advice** Nearside Front Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Nearside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
8 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	8 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-03-31
Last registration	2024-04-04
Complete history	<a href="#">See info</a>



Registration #1	2017-03-31	25 mi
Registration #2	2020-03-02	49.431 mi
Registration #3	2020-03-03	49.431 mi
Registration #4	2021-04-09	72.740 mi
Registration #5	2021-04-09	72.740 mi
Registration #6	2022-03-29	95.277 mi
Registration #7	2022-03-29	95.277 mi
Registration #8	2023-03-29	117.814 mi
Registration #9	2023-03-29	117.814 mi
Registration #10	2024-03-28	140.351 mi
Registration #11	2024-03-28	140.351 mi
Registration #12	2024-04-04	162.888 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	79%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1563 mm
Height	1472 mm
Length	4585 mm
Wheel base	2730 mm
Kerb weight	1300 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JCAN3155976