





report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Grey
Year of manufacture	2002
Top speed	140 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	201 BHP	
Max. torque	249 Nm at 4.000 rpm	
Engine capacity	2.496 cc	
Cylinders	6	
Fuel type	Petrol	
Consumption city	19.3 mpg	
Consumption extra urban	35.8 mpg	
Consumption combined	27.4 mpg	
CO2 emission	249 g/km	
CO2 label	L	



CarCheck.co.uk page 1/16




Internet history

Entry 1

Date 2021-06-04

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2023-11-28
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	30
Total items failed	20

MOT #24	2024-04-12 08:31	
MOT test number	875586743623	
Result	X Failed	
Advice Osf/nsf headlamps obscured		
Fail Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of di	rt osr/nsr (5.3.4 (b) (ii))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Fail Vehicle structure or chassis has excessive corrosion, seriously affecting its st body mounting osr/nsr inner sills at rear corroded (6.2.2 (d) (i))	trength within 30cm of a	

MOT #23	2022-11-16 11:38
MOT test number	791351594208
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))

MOT #22		2021-11-29 15:51
MOT test	number	314499143192
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/16



MOT #21 2020-11-27 14:59

MOT test number 263969290495

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20 2020-11-27 09:41

MOT test number 770678059436

Result X Failed

Fail Headlamp aim projected beam image is obviously incorrect both headlamp lenses faded (4.1.2 (c))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2019-11-29 16:12

MOT test number 212380041797

Result
✓ Passed

Advice Oil leak

MOT #18 2019-11-29 09:10

MOT test number 405899278387

Result X Failed

Advice Oil leak

Fail Nearside Rear Tyre has ply or cords exposed split on inner sidewall (5.2.3 (d) (ii))

Fail Headlamp aim projected beam image is obviously incorrect both lenses faded (4.1.2 (c))

CarCheck.co.uk page 4/16



MOT #17 2018-11-19 13:04

MOT test number 885482390768

Result ✓ Passed

Advice Both front headlight lenses faded

MOT #16 2018-11-17 08:51

MOT test number 530916102371

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall, & tyre perrished in tread area (5.2.3 (d) (i))

Advice Oil leak

Advice Both front headlight lenses faded

MOT #15 2017-11-16 10:51

MOT test number 609869226059

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit cracking up outer edges and inner surface (4.1.E.1)

Advice Tyre worn close to the legal limit both sides inner and outer edges cracking up (4.1.E.1)

Advice Offside Front drivers door safety strap broken

MOT #14 2016-11-28 15:20

MOT test number 718839855664

Advice N/s rear tyre perrished

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

CarCheck.co.uk page 5/16



Result

Advice

RX52HYF report date: 2024-03-29

✓ Passed

MOT #13 2015-11-06 11:02

MOT test number 116180539774

Result ✓ Passed

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #12 2014-11-13 13:55

MOT test number 246097314350

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice

Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #11 2013-10-25 15:49

MOT test number 688428193207

Result ✓ Passed

CarCheck.co.uk page 6/16



Fail

MOT #9

MOT #7

ingress of dirt (2.4.G.2)

RX52HYF

report date: 2024-03-29

2012-10-12 09:02

2010-11-17 10:44

MOT #10 2013-10-22 09:32 **MOT** test number 986255593264 Result **X** Failed Fail Electronic parking brake warning indicates a malfunction (3.1.7) Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Notice Rear brake discs worn Fail Offside rear brake recording little or no effort (3.7.B.5a) Fail Nearside Rear Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Offside Rear Tie bar/rod has excessive play in a pin/bush (2.4.G.2) Fail Parking brake not fitted on at least two wheels (3.1.1) Notice Noise coming from front of engine Nearside rear brake recording little or no effort (3.7.B.5a) Fail Fail Parking brake: efficiency below requirements (3.7.B.7)

1.01 #3	2012 10 12 03.02
MOT test number	415766782253
Result	✓ Passed
MOT #8	2011-10-28 08:53

Offside Rear Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the

MOT test number	828041701346
Result	✓ Passed

MOT test number	410161620474
Result	✓ Passed

CarCheck.co.uk page 7/16



RX52HYF

report date: 2024-03-29

MOT #6	2009-11-17 09:35
MOT test number	642691429384
Result	✓ Passed
MOT #5	2008-11-13 13:43
MOT test number	423778618338
Result	✓ Passed
MOT #4	2008-11-13 10:38
MOT test number	682738318352
Result	★ Failed
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)	
Fail Anti-lock braking system warning lamp does not illuminate (3.4.1b)	
Notice Hand brake warning lamp illuminated	
Advice Rear brake disc slightly scored (3.5.1h)	
Fail Offside rear parking brake recording little or no effort (3.7.B.6a)	

MOT #3	2007-11-20 09:51
MOT test number	873454427367
Result	✓ Passed

MOT #2		2006-11-17 09:09
MOT test	number	893091726348
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/16



RX52HYF

report date: 2024-03-29

 MOT #1
 2005-11-09 09:05

 MOT test number
 290073715361

Result ✓ Passed

CarCheck.co.uk page 9/16



Tax & MOT check



Expired: 28 November 2023

X MOT

Tax expired: 28 March 2024

Tax status

Expired at 28 March 2024

Days left 32 days too late

MOT expiry date 28 November 2023

Full MOT history See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

· ·		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		λ R
manage of the same		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 14/16



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-10-23
Last registration	2024-04-12
Complete history	See info



Registration #1	2002-10-23	21 mi
Registration #2	2005-11-09	15.063 mi
Registration #3	2006-11-17	21.056 mi
Registration #4	2007-11-20	29.352 mi
Registration #5	2008-11-13	31.869 mi
Registration #6	2008-11-13	31.892 mi
Registration #7	2009-11-17	46.266 mi
Registration #8	2010-11-17	57.729 mi
Registration #9	2011-10-28	62.602 mi
Registration #10	2012-10-12	66.456 mi
Registration #11	2013-10-22	70.623 mi
Registration #12	2013-10-25	70.654 mi
Registration #13	2014-11-13	74.264 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		10.777 au
Registration #19		11,177 es
Registration #19 Registration #20		11.777 es
		11,777 ea 11,777 ea 11,777 ea
Registration #20		11,777 ea 11,777 ea 11,777 ea
Registration #20 Registration #21		71,777 es 71,777 es 71,777 es 71,777 es
Registration #20 Registration #21 Registration #22		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #20 Registration #21 Registration #22 Registration #23		11.00 mi 11.00 mi 11.00 mi 11.00 mi 11.00 mi

CarCheck.co.uk page 15/16



Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm

Additional information

Number of axles	2
Engine number	287880376JB

CarCheck.co.uk page 16/16