



report date: 2024-03-29

General information

Make	FORD
Model	FUSION 16V ZETEC
Colour	Blue
Year of manufacture	2003
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	158 g/km
CO2 label	G





MOT history

MOT expiry date	2025-03-14
MOT pass rate	76 %
MOT passed	19
Failed MOT tests	6
Total advice items	20
Total items failed	17

MOT #25	2024-03-14 14:37
MOT test number	179657979040
Result	✓ Passed
Next expiry date	2025-03-14
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Coolant leak

MOT #24	2023-03-14 14:34
MOT test number	219822341532
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge nsf + osf (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
Minor	Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #23	2022-03-15 11:26
MOT test number	574564453489
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Suspension arm ball joint dust cover severely deteriorated NSF + OSF (5.3.4 (b) (i))

**MOT #22** 2021-03-11 14:11**MOT test number** 991863630252**Result** ✓ Passed**MOT #21** 2020-01-29 11:57**MOT test number** 995401690997**Result** ✓ Passed**MOT #20** 2020-01-27 14:51**MOT test number** 704438850304**Result** ✗ Failed

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #19 2019-01-11 16:54**MOT test number** 989986585421**Result** ✓ Passed

- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #18** 2018-01-13 09:10**MOT test number** 160534580954**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #17** 2017-01-07 09:17**MOT test number** 744589901551**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**MOT #16** 2016-01-09 10:32**MOT test number** 541567102302**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #15** 2015-01-13 17:42**MOT test number** 225473115031**Result** ✓ Passed

**MOT #14** 2015-01-13 17:42**MOT test number** 388143515082**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #13** 2014-02-04 16:05**MOT test number** 209205734075**Result** ✓ Passed**MOT #12** 2014-02-04 16:05**MOT test number** 847225334088**Result** ✗ Failed**Pass with rectification** Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #11** 2013-02-13 12:35**MOT test number** 185444043445**Result** ✓ Passed**MOT #10** 2012-02-14 14:28**MOT test number** 136135642494**Result** ✓ Passed**MOT #9** 2011-02-12 11:54**MOT test number** 108913641410**Result** ✓ Passed**MOT #8** 2010-02-17 10:49**MOT test number** 294198640056**Result** ✓ Passed

**MOT #7** 2009-03-17 14:58**MOT test number** 874726479071**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2008-03-26 11:58**MOT test number** 503996588030**Result** ✓ Passed**MOT #5** 2008-03-26 11:58**MOT test number** 151146088440**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2007-03-21 12:21**MOT test number** 462160987010**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #3** 2007-03-21 12:21**MOT test number** 102180487423**Result** ✓ Passed**MOT #2** 2006-04-04 08:57**MOT test number** 703934396028**Result** ✓ Passed



MOT #1	2006-04-04 08:57
MOT test number	883684296026
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.6.D2)
Pass with rectification	Offside Headlamp aim too low (1.6.D2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-02-05
Last registration	2024-03-14
Complete history	See info



Registration #1	2003-02-05	13 mi
Registration #2	2006-04-04	12.882 mi
Registration #3	2007-03-21	16.453 mi
Registration #4	2008-03-26	19.310 mi
Registration #5	2009-03-17	22.041 mi
Registration #6	2010-02-17	25.721 mi
Registration #7	2011-02-12	27.582 mi
Registration #8	2012-02-14	29.048 mi
Registration #9	2013-02-13	30.757 mi
Registration #10	2014-02-04	31.690 mi
Registration #11	2015-01-13	32.098 mi
Registration #12	2016-01-20	32.557 mi
Registration #13	2017-01-20	33.077 mi
Registration #14	2018-01-20	33.657 mi
Registration #15	2019-01-20	34.297 mi
Registration #16	2020-01-20	34.997 mi
Registration #17	2021-01-20	35.757 mi
Registration #18	2022-01-20	36.577 mi
Registration #19	2023-01-20	37.457 mi
Registration #20	2024-01-20	38.397 mi
Registration #21	2024-03-14	38.997 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1463 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1076 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	3E55488