





General information

| Make | FIAT |
|---------------------|-------------------------|
| Model | 500 L MULTIJET POP STAR |
| Colour | Grey |
| Year of manufacture | 2013 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 85 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.500 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 110 g/km |
| CO2 label | В |







Internet history

| Entry | 1 |
|-------|---|
| Date | |

Pictures

2021-10-06

16

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-10-26 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #10 | 2023-10-25 13:54 |
|--|------------------|
| MOT test number | 526833288322 |
| Result | ✓ Passed |
| Next expiry date 2024-10- | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #9 | 2023-10-25 13:54 |
|--|------------------|
| MOT test number | 960575772354 |
| Result | × Failed |
| Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #8 | 2022-10-19 12:50 |
|-----------------|------------------|
| MOT test number | 223439171798 |
| Result | ✓ Passed |

| MOT #7 | 2021-10-27 15:30 |
|-----------------|------------------|
| MOT test number | 354032246340 |
| Result | ✓ Passed |





| MOT #6 | | 2021-10-26 12:01 |
|----------|--|------------------|
| MOT test | number | 404260197753 |
| Result | | 🗙 Failed |
| MAJOR | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |
| | | |
| MOT #5 | | 2020-12-15 11:24 |
| MOT test | number | 629281730998 |
| Result | | ✓ Passed |
| Advice | Tyre worn close to legal limit/worn on edge nearside front (5.2.3 (e)) | |
| | | |
| MOT #4 | | 2019-07-01 13:20 |

| MOT test | number | 440126973301 |
|----------|--|--------------|
| Result | | ✓ Passed |
| Advice | Brake disc worn, but not excessively Nearside Rear and Offside Rear (1.1.14 (a) (i)) | |

| MOT #3 | 2018-07-23 14:14 |
|-----------------|------------------|
| MOT test number | 151641131957 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2017-11-23 09:29 |
| MOT test number | 839475005340 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2016-12-02 12:26 |
|-----------------|------------------|
| MOT test number | 793446726084 |
| Result | ✓ Passed |



Tax & MOT check

| Taxed Taxed Tax due: 1 October 2024 | ✓ MOT Expires: 26 October 2024 |
|--|---|
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 26 October 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Dumage 2 | E E E E |
| Date | J. |
| Category | amer |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and a second | |
|--|-------------|
| ********* | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | 7 |
| Current registration | |
| | |
| Plate since | |
| Plate since Current registration | |
| Plate since Carrent registration Plate since | 8000-20-20 |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-12-31 |
| Last registration | 2023-10-25 |
| Complete history | See info |



| Registration #1 | 2013-12-31 | 11 mi |
|------------------|------------|------------|
| Registration #2 | 2016-12-02 | 27.239 mi |
| Registration #3 | 2017-11-23 | 38.911 mi |
| Registration #4 | 2018-07-23 | 44.944 mi |
| Registration #5 | 2019-07-01 | 49.748 mi |
| Registration #6 | 2020-12-15 | 55.757 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |
| Registration #10 | | 10.200 est |
| | | |
| Registration #11 | | 11.777 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 78% |
| Pedestrian | 65% |
| Safety systems | 71% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2018 mm |
| Height | 1667 mm |
| Length | 4147 mm |
| Wheel base | 2612 mm |
| Kerb weight | 1315 kg |
| Max. allowed weight | 1875 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 4939234 |