



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	Turquoise
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-10
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	37
Total items failed	8

MOT #15 2023-05-11 18:23

MOT test number 707842601414

Result ✓ Passed

Next expiry date 2024-05-10

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush slight play (5.3.2 (c))
- Advice** Oil leak, but not excessive slight (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))

MOT #14 2023-05-10 09:18

MOT test number 765678220984

Result ✗ Failed

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush slight play (5.3.2 (c))
- MAJOR** Front Exhaust emissions likely to be affected by an exhaust leak at flex pipe [broken] (8.2.1.1 (b))
- Advice** Oil leak, but not excessive slight (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))
- MAJOR** Emissions unable to be completed due to condition of exhaust [major leak] (8.2.1.2 (d))

**MOT #13** 2022-04-21 10:20**MOT test number** 910260155669**Result** Passed**MOT #12** 2022-04-21 10:20**MOT test number** 191445286972**Result** Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2021-03-10 16:40**MOT test number** 633915123102**Result** Passed**MOT #10** 2021-03-10 13:20**MOT test number** 502723965050**Result** Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2020-03-18 11:05**MOT test number** 780029303116**Result** Passed

**MOT #8** 2020-03-16 12:03**MOT test number** 528314053643**Result** ✗ Failed**Advice** Central Front Exhaust mounting defective (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2019-03-23 12:19**MOT test number** 499760613595**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Sump corroded**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on inside edge (5.2.3 (e))

**MOT #6**

2019-03-23 12:19

MOT test number

714777044197

Result**✗ Failed****Advice** Sump corroded**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on inside edge (5.2.3 (e))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5**

2018-03-19 15:41

MOT test number

498224078466

Result**✓ Passed****Advice** Offside Rear Tyre has a nail in the tread**MOT #4**

2018-03-19 09:07

MOT test number

492496257590

Result**✗ Failed****Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre has a nail in the tread

**MOT #3** 2017-03-21 09:31**MOT test number** 583213742180**Result** ✓ Passed**Advice** Front tyres low**Advice** Front brake discs corroded**MOT #2** 2016-03-25 13:51**MOT test number** 177633023251**Result** ✓ Passed**Advice** Both sides rear hand brake cables outer cover split**MOT #1** 2016-03-23 14:00**MOT test number** 216324686709**Result** ✗ Failed**Fail** Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Advice** Both sides rear hand brake cables outer cover split**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
10 May 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-29
Last registration	2023-05-11
Complete history	See info



Registration #1	2013-03-29	18 mi
Registration #2	2016-03-23	13.767 mi
Registration #3	2016-03-25	13.807 mi
Registration #4	2017-03-21	24.965 mi
Registration #5	2018-03-19	34.096 mi
Registration #6	2018-03-19	34.096 mi
Registration #7	2019-03-23	40.509 mi
Registration #8	2019-03-23	40.509 mi
Registration #9	2020-03-16	45.823 mi
Registration #10	2020-05-20	55,557 mi
Registration #11	2020-05-20	55,557 mi
Registration #12	2020-05-20	55,557 mi
Registration #13	2020-05-20	55,557 mi
Registration #14	2020-05-20	55,557 mi
Registration #15	2020-05-20	55,557 mi
Registration #16	2020-05-20	55,557 mi
Registration #17	2020-05-20	55,557 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

Engine number

0341597