





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VERSO D-4D T3
Colour	Grey
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	Н





FN57GMU report date: 2024-03-29

Internet history

Entry 1	
Date	2021-02-05
Pictures	4
Listing price	View report







source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	38
Total items failed	9

MOT #19	2024-02-08 10:26
MOT test number	974771355253
Result	✓ Passed
Next expiry date	2025-02-07
Advice Rear Parking brake efficiency only just met. It would appear that th adjustment or repair. b oth (1.4.2 (a) (i))	e braking system requires

MOT #18	2022-11-18 16:46
MOT test number	786905337765
Result	✓ Passed
MOT #17	2022-11-18 16:00
MOT test number	805371971511
Result	🗙 Failed

Fail Brake lever has insufficient reserve travel (1.1.2 (a))





MOT #16	2022-11-18 11:14
MOT test number	965766795965
Result	🗙 Failed
Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minin required is 1.0mm (5.2.3 (e))	num depth
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimu is 1.0mm (5.2.3 (e))	um depth required
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #15	2021-11-09 09:09
MOT test number	737905402625
Result	✓ Passed

MOT #14	2020-10-24 07:36
MOT test number	735399856289
Result	✓ Passed

MOT #13		2019-11-15 11:48
MOT test	number	316192752190
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin boarderline (1.1.13 (a) (ii))	
Advice	Handbrake requires adjustment soon	

MOT #12	2018-11-14 10:52
MOT test number	974489492495
Result	✓ Passed





MOT #11		2017-11-14 14:05
MOT test number		107012614510
Result		✓ Passed
Advice Nearsid	e Front Tyre worn close to the legal limit wearing on outer edge (4.1.E.1)	
Advice Offside	Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Parking	brake lever has little reserve travel (3.1.6b)	

MOT #10		2017-11-13 10:15
MOT test	MOT test number	
Result		🗙 Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Fail F	ront Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit wearing on outer edge (4.1.E.1)	

MOT #9		2016-11-15 14:37
MOT test	number	854109887992
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit Inner and outer edges (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin Around 1-2 thousand miles (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit Inner and outer edges (4.1.E.1)	





MOT #8		2015-11-05 14:07
MOT test	number	309328878774
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.3	1i)
Advice	Both front tyres wearing on inner and outer edges	

MOT #7		2015-11-05 13:00
MOT test	number	506718990500
Result		🗙 Failed
Fail E	xhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.	3.3b)
Advice	Both front tyres wearing on inner and outer edges	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	i)

MOT #6	2014-11-10 13:18
MOT test	number 526254214386
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Parking brake lever has little reserve travel (3.1.6b)





МОТ #5	2014-11-10 13:18	
MOT test number	119864914353	
Result	× Failed	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Parking brake lever has little reserve travel (3.1.6b)		
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #4		2013-11-12 13:42
MOT test	number	356146513396
Result		✓ Passed
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Advise nsf wiper rubber split	

МОТ #3	2012-11-15 10:11
MOT test number	677740522389
Result	✓ Passed



F	N5	57	G	Μ	U
	repo	rt da	te: 2	024-0)3-29

MOT #2		2011-11-15 10:27
MOT test number		257469911354
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Front discs worn	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #1	2010-11-11 09:03
MOT test number	333865210339
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ MOT
Tax status	Expires: 7 February 2025 Valid until 1 May
Days left	2
MOT expiry date Full MOT history	7 February 2025 See MOT history

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E Stand
Date	*
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 11.111
Average private trade value	4 10 200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-11-19
Last registration	2024-02-08
Complete history	See info



Registration #1	2007-11-19	21 mi
Registration #2	2010-11-11	43.543 mi
Registration #3	2011-11-15	56.614 mi
Registration #4	2012-11-15	68.998 mi
Registration #5	2013-11-12	78.175 mi
Registration #6	2014-11-10	84.557 mi
Registration #7	2015-11-05	90.624 mi
Registration #8	2015-11-05	90.624 mi
Registration #9	2016-11-15	96.520 mi
Registration #10	2017-11-13	101.988 mi
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.117 est
Registration #19		11.777 esi
Registration #20		11.277 est







Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/15

Number of axles	2
Engine number	2AD521824