



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE
Colour	Silver
Year of manufacture	-
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-09
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-05
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #22</b>	2022-02-19 10:34
<b>MOT test number</b>	503551667152
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-02-21
<b>Advice</b>	Front Exhaust mounting defective (6.1.2 (a))
<b>Minor</b>	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
<b>Advice</b>	Offside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #21</b>	2022-02-19 10:34
<b>MOT test number</b>	196788736148
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Minor</b>	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
<b>Advice</b>	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
<b>Advice</b>	Front Exhaust mounting defective (6.1.2 (a))
<b>Pass with rectification</b>	Offside Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #20**

2021-02-22 13:04

**MOT test number**

399723120552

**Result**

✓ Passed

- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Power steering component has slight seepage from a component (2.1.5 (a))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #19**

2021-02-22 13:04

**MOT test number**

467133302407

**Result**

✗ Failed

- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Power steering component has slight seepage from a component (2.1.5 (a))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18**

2020-02-15 14:17

**MOT test number**

883128223263

**Result**

✓ Passed

- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front Anti-roll bar ball joint has slight play both side (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17**

2020-02-15 12:43

**MOT test number**

273267055920

**Result****✗ Failed**

**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps both side (4.7.2 (a))

**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Front Anti-roll bar ball joint has slight play both side (5.3.4 (a) (i))

**MOT #16**

2019-02-04 14:52

**MOT test number**

230880126187

**Result****✓ Passed**

**Advice** Brake pipe corroded, covered in grease or other material front to rear & rear (1.1.11 (c))

**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #15**

2019-02-04 14:52

**MOT test number**

428822869061

**Result****✗ Failed**

**Advice** Brake pipe corroded, covered in grease or other material front to rear & rear (1.1.11 (c))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #14**

2018-02-19 13:24

**MOT test number**

468032017601

**Result**

✓ Passed

- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear coil spring worn both (2.4.C.1b)

**MOT #13**

2018-02-19 13:24

**MOT test number**

177568982384

**Result**

✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear coil spring worn both (2.4.C.1b)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12**

2017-01-30 15:47

**MOT test number**

715274706636

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside dipped beam headlight output poor
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2017-01-30 09:33

**MOT test number**

568333854139

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside dipped beam headlight output poor
- Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)

**MOT #10**

2016-01-14 14:01

**MOT test number**

825191351906

**Result****✓ Passed**

- Advice** Offside Power steering component(s) has slight seepage from a seal (2.3.3b)
- Advice** Both front tyres worn on inner edges.
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2015-01-09 16:44

**MOT test number**

657739505014

**Result****✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-01-09 16:44**MOT test number** 989679805025**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #7** 2014-01-13 12:34**MOT test number** 629473014019**Result** ✓ Passed**MOT #6** 2014-01-11 09:39**MOT test number** 698241314060**Result** ✗ Failed

- Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-01-23 14:53**MOT test number** 915193323079**Result** ✓ Passed

- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)





<b>MOT #4</b>	2012-01-09 17:53
---------------	------------------

<b>MOT test number</b>	417539402098
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #3</b>	2011-01-10 11:40
---------------	------------------

<b>MOT test number</b>	908750411010
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-01-20 10:37
---------------	------------------

<b>MOT test number</b>	242280220077
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #1</b>	2008-08-18 12:00
---------------	------------------

<b>MOT test number</b>	214601438216
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-01
Last registration	2022-02-19
Complete history	<a href="#">See info</a>



Registration #1	2005-09-01	26 mi
Registration #2	2008-08-18	5.815 mi
Registration #3	2010-01-20	18.245 mi
Registration #4	2011-01-10	26.315 mi
Registration #5	2012-01-09	33.762 mi
Registration #6	2013-01-23	38.761 mi
Registration #7	2014-01-11	53.431 mi
Registration #8	2014-01-13	53.432 mi
Registration #9	2015-01-09	71.867 mi
Registration #10	2016-01-14	89.599 mi
Registration #11	2017-01-30	98.167 mi
Registration #12	2017-01-30	98.167 mi
Registration #13	2018-01-01	116.602 mi
Registration #14	2018-01-01	116.602 mi
Registration #15	2018-01-01	116.602 mi
Registration #16	2018-01-01	116.602 mi
Registration #17	2018-01-01	116.602 mi
Registration #18	2018-01-01	116.602 mi
Registration #19	2018-01-01	116.602 mi
Registration #20	2018-01-01	116.602 mi
Registration #21	2018-01-01	116.602 mi
Registration #22	2018-01-01	116.602 mi
Registration #23	2018-01-01	116.602 mi
Registration #24	2018-01-01	116.602 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	320744