



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | CITROEN        |
| Model               | DS4 HDI DSPORT |
| Colour              | Black          |
| Year of manufacture | 2014           |
| Top speed           | 132 mph        |
| 0 - 60 mph          | 9.3 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 161 BHP             |
| Max. torque             | 340 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 46.3 mpg            |
| Consumption extra urban | 67.3 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 130 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-06                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-11-16 |
| MOT pass rate      | 88 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 1          |
| Total advice items | 19         |
| Total items failed | 0          |

## MOT #8 2023-11-16 15:19

MOT test number 295332565864

Result ✓ Passed

Next expiry date 2024-11-16

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre on 3 mm wear bars (5.2.3 (e))

## MOT #7 2023-11-14 13:58

MOT test number 318132105679

Result ✗ Failed

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Nearside Front Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre on 3 mm wear bars (5.2.3 (e))

## MOT #6 2022-11-15 09:11

MOT test number 580575638689

Result ✓ Passed

**MOT #5**

2021-11-17 12:13

**MOT test number**

560729783405

**Result**

✓ Passed

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4**

2020-10-30 10:52

**MOT test number**

532227995565

**Result**

✓ Passed

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice**

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #3**

2019-10-31 10:40

**MOT test number**

277277590505

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



|                 |   |
|-----------------|---|
| MOT #2          | 2018-10-18 08:07  |
| MOT test number | 375374359277  |
| Result          | ✓ Passed  |
| Advice          | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice          | Windscreen wipers smearing  |
| Advice          | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))                          |
| Advice          | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2017-10-25 12:51 |
| MOT test number | 630622767876     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
16 November 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 277                             |
| <b>MOT expiry date</b>  | 16 November 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | D          |
| <b>Single payment (12 months)</b>              | £ 150,00,- |
| <b>Single six month payment</b>                | £ 82,50,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 157,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>KP64UBX</b> |
| Plate since          | 2024-03-29     |
| Current registration | <b>KP64UBX</b> |
| Plate since          | 2024-03-29     |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |            |        |
|-------------------|------------|--------|
| Finance company   | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type    | XXXXXXXXXX | XXXXXX |
| Agreement term    | XXXXXXXXXX | XXXXXX |
| Agreement number  | XXXXXXXXXX | XXXXXX |
| Contact info      | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 10                       |
| First mileage registration | 2014-10-30               |
| Last registration          | 2023-11-16               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2014-10-30 | 9 mi      |
| Registration #2  | 2017-10-25 | 29.369 mi |
| Registration #3  | 2018-10-18 | 46.203 mi |
| Registration #4  | 2019-10-31 | 61.922 mi |
| Registration #5  | 2020-10-30 | 72.374 mi |
| Registration #6  | 2020-10-30 | 72.374 mi |
| Registration #7  | 2020-10-30 | 72.374 mi |
| Registration #8  | 2020-10-30 | 72.374 mi |
| Registration #9  | 2020-10-30 | 72.374 mi |
| Registration #10 | 2020-10-30 | 72.374 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 90%                             |
| Children       | 80%                             |
| Pedestrian     | 43%                             |
| Safety systems | 97%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1810 mm |
| Height              | 1523 mm |
| Length              | 4275 mm |
| Wheel base          | 2612 mm |
| Kerb weight         | 1320 kg |
| Max. allowed weight | 1880 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | DYZE4124651      |