



SN65UGT


report date: 2024-03-28

General information

Make	FORD
Model	KA TITANIUM
Colour	Black
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-22
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-29
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #10	2023-11-27 16:32
MOT test number	661095245752
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2023-11-27 11:44

MOT test number

304402421237

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
- Fail** Emissions unable to be completed (8.2.1.2 (d))

MOT #8

2022-11-24 14:13

MOT test number

839994366492

Result**✓ Passed**

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7

2022-11-24 09:27

MOT test number

497513073946

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #6** 2021-11-11 16:37**MOT test number** 635600079073**Result** ✓ Passed**MOT #5** 2021-11-11 10:58**MOT test number** 666832785885**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #4** 2020-11-19 09:02**MOT test number** 120323347609**Result** ✓ Passed**MOT #3** 2019-11-08 15:59**MOT test number** 758686363149**Result** ✓ Passed**MOT #2** 2019-11-08 13:04**MOT test number** 271248566948**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))



MOT #1	2018-11-06 13:06
MOT test number	795458814889
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge tyre at 3mm (5.2.3 (e))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-30
Last registration	2023-11-27
Complete history	See info



Registration #1	2015-11-30	27 mi
Registration #2	2018-11-06	13.148 mi
Registration #3	2019-11-08	21.211 mi
Registration #4	2019-11-08	21.211 mi
Registration #5	2020-11-19	29.813 mi
Registration #6	2020-11-19	29.813 mi
Registration #7	2020-11-19	29.813 mi
Registration #8	2020-11-19	29.813 mi
Registration #9	2020-11-19	29.813 mi
Registration #10	2020-11-19	29.813 mi
Registration #11	2020-11-19	29.813 mi
Registration #12	2020-11-19	29.813 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424