



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Red
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	141 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	31.0 mpg
Consumption combined	26.9 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2022-12-24
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-03-14
Pictures	37
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #20	2022-06-10 12:34
MOT test number	830227862112
Result	✓ Passed
Next expiry date	2023-06-09
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #19	2022-06-08 12:06
MOT test number	723595576849
Result	✗ Failed
Fail	Nearside Rear Valve stem seriously damaged (5.2.3 (j))
Fail	Nearside Headlamp aim too high (4.1.2 (a))
Fail	Offside Rear Valve stem seriously damaged (5.2.3 (j))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside headlamp bracket broken
Fail	Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #18	2021-04-20 09:32
MOT test number	827417915714
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material to brake hose (1.1.11 (c))
Advice	Rear Registration plate deteriorated but not likely to be misread fading (0.1 (b))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material to hub (1.1.11 (c))

MOT #17	2020-04-29 13:02
MOT test number	969579188943
Result	✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16**

2020-04-28 15:58

MOT test number

898902226093

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15**

2019-04-19 09:28

MOT test number

825414556141

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material from hose marked (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lip (1.1.14 (a) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #14**

2019-04-16 09:16

MOT test number

474358820618

Result

✗ Failed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Accelerator pedal sticking slightly**Fail** Rear Anti-roll bar pin or bush excessively worn both d bushes (5.3.4 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits 1.142 (8.2.1.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lip (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material from hose marked (1.1.11 (c))

**MOT #13** 2018-04-05 15:56**MOT test number** 119782547206**Result** ✓ Passed

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #12 2017-02-15 09:33**MOT test number** 329096891780**Result** ✓ Passed

Advice High handbrake travel

Advice Nearside front outer constant velocity gaiter slightly deteriorated

MOT #11 2016-02-19 15:41**MOT test number** 311951817965**Result** ✓ Passed

Advice Evidence of accident damage to central frontal area

MOT #10 2016-02-19 13:26**MOT test number** 557649740458**Result** ✗ Failed

Fail Offside Rear Brake pipe excessively corroded to hose (3.6.B.2c)

Fail Headlamp aim too high both (1.8)

MOT #9 2015-02-23 11:31**MOT test number** 177414355425**Result** ✓ Passed

**MOT #8** 2015-02-23 11:31**MOT test number** 149794055095**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #7** 2014-02-11 17:11**MOT test number** 588702444002**Result** ✓ Passed**MOT #6** 2014-02-11 14:27**MOT test number** 356642844042**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-02-18 09:15**MOT test number** 446109943013**Result** ✓ Passed**Notice** Front tyres low worn on inner edges**MOT #4** 2012-02-23 12:57**MOT test number** 148844852426**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-02-22 16:40**MOT test number** 965743551072**Result** ✓ Passed



MOT #2	2010-02-24 12:10
MOT test number	572715950090
Result	✓ Passed

MOT #1	2009-02-19 13:09
MOT test number	720580559087
Result	✓ Passed

Notice N/S/F Tyre is down to minimum 1.6 mm and is worn on inner edge.



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-31
Last registration	2022-06-10
Complete history	See info



Registration #1	2006-03-31	13 mi
Registration #2	2009-02-19	17.133 mi
Registration #3	2010-02-24	23.069 mi
Registration #4	2011-02-22	27.775 mi
Registration #5	2012-02-23	31.510 mi
Registration #6	2013-02-18	34.495 mi
Registration #7	2014-02-11	38.135 mi
Registration #8	2014-02-11	38.135 mi
Registration #9	2015-02-23	41.176 mi
Registration #10	2016-02-19	44.368 mi
Registration #11	2016-02-19	44.368 mi
Registration #12	2016-02-19	44.368 mi
Registration #13	2016-02-19	44.368 mi
Registration #14	2016-02-19	44.368 mi
Registration #15	2016-02-19	44.368 mi
Registration #16	2016-02-19	44.368 mi
Registration #17	2016-02-19	44.368 mi
Registration #18	2016-02-19	44.368 mi
Registration #19	2016-02-19	44.368 mi
Registration #20	2016-02-19	44.368 mi
Registration #21	2016-02-19	44.368 mi
Registration #22	2016-02-19	44.368 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1635 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1349 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	G4ED5286490