



report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET TREKKING
Colour	Black
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2


Date	2021-09-08
Pictures	23
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-06
Pictures	23
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-12-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	29
Total items failed	7

MOT #10	2023-12-12 14:55
----------------	------------------

MOT test number	758645790548
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2024-12-11
-------------------------	------------

- Advice** Brake hose has slight corrosion to ferrule ALL (1.1.12 (f) (i))
- Advice** Exhaust corroded
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement BOTH rear trailing arm front bushes (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Both front lower suspension arms very corroded
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** General underside corrosion
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Daytime running lamp not working

**MOT #9**

2023-12-09 09:14

MOT test number

312765490421

Result**✗ Failed**

- Fail** Headlamp aim too low BOTH (4.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Brake hose has slight corrosion to ferrule ALL (1.1.12 (f) (i))
- Advice** Both front lower suspension arms very corroded
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement BOTH rear trailing arm front bushes (5.3.4 (a) (i))
- Advice** General underside corrosion
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Daytime running lamp not working
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Exhaust corroded
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #8** 2022-09-12 10:56**MOT test number** 807478431484**Result** ✓ Passed

- Advice** Front Upper Strut top mounts noisy when rotated - Both
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Exhaust system corroded
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Coil spring corroded Both (5.3.1 (b) (i))

MOT #7 2021-09-06 10:03**MOT test number** 991633502284**Result** ✓ Passed**MOT #6** 2021-09-03 14:08**MOT test number** 250153765644**Result** ✗ Failed

- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #5 2021-02-03 16:40**MOT test number** 164389592166**Result** ✓ Passed**MOT #4** 2019-03-05 09:40**MOT test number** 702584731405**Result** ✓ Passed



MOT #3	2018-06-11 14:27
MOT test number	830910085570
Result	✓ Passed

MOT #2	2018-06-11 09:22
MOT test number	184806085288
Result	✗ Failed
<div><div>Fail</div> Rear Brakes imbalanced across an axle (1.2.1 (b) (i))</div> <div><div>Advice</div> Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))</div> <div><div>Fail</div> Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))</div>	

MOT #1	2017-03-24 16:08
MOT test number	229630357683
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 December 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-01
Last registration	2023-12-12
Complete history	See info



Registration #1	2014-04-01	10 mi
Registration #2	2017-03-24	46.253 mi
Registration #3	2018-06-11	52.722 mi
Registration #4	2018-06-11	52.722 mi
Registration #5	2019-03-05	60.555 mi
Registration #6	2021-02-03	77.993 mi
Registration #7	2021-09-03	80.608 mi
Registration #8	2023-12-12	80.608 mi
Registration #9	2023-12-12	80.608 mi
Registration #10	2023-12-12	80.608 mi
Registration #11	2023-12-12	80.608 mi
Registration #12	2023-12-12	80.608 mi
Registration #13	2023-12-12	80.608 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1679 mm
Length	4270 mm
Wheel base	2612 mm
Kerb weight	1315 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5250786