





report date: 2024-03-28

General information

Make	BMW
Model	7 SERIES 730D SE
Colour	Grey
Year of manufacture	2010
Top speed	153 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	241 BHP
Max. torque	540 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	1



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-30

Pictures 69

Listing price <u>View report</u>










source: yesauto.com

Entry 1

Date 2021-09-01

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



SM60CSZ report date: 2024-03-28

MOT history

MOT expiry date	2024-04-16
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	6
Total items failed	9

MOT #12	2023-04-17 13:49
MOT test number	895503531335
Result	✓ Passed
Next expiry date	2024-04-16

MOT #11	2021-09-02 08:04
MOT test number	121242857745
Result	✓ Passed

MOT #10	2021-02-05 10:36
MOT test	
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 275/40/19 rsc (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2020-02-01 10:02
MOT test number	690281278092
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8

MOT test number

519548152343

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-02-01 14:15 **MOT** test number 382654096872 Result **X** Failed Fail Offside Rear Direction indicator light intensity significantly reduced (4.4.3 (a)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Rear Position lamp not working (4.2.1 (a))

MOT #6	2017-08-07 14:54
MOT test number	262134855635
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2017-08-07 07:45
MOT test number	485509945092
Result	× Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Rear Tyre has ply or cords exposed inner edge (4.1.D.1b)	
Fail Nearside Rear coil spring broken (2.4.C.1a)	

Fail Nearside Rear coil spring broken (2.4.C.1a)	
MOT #4	2016-08-12 13:19
MOT test number	679151722857
Result	✓ Passed
MOT #3	2015-08-06 15:03
MOT test number	138718315281
Result	✓ Passed
MOT #2	2014-06-05 09:34
MOT test number	535866354135
Result	✓ Passed
MOT #1	2013-08-01 09:01
MOT test number	398833213240
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax expired: 30 September 2023

X MOT

Expired: 16 April 2024

Tax status	Expired at 30 September
Days left	213 days too late
MOT expiry date	16 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
	1
Band	ı
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SM60CSZ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report h	

THE STATE OF THE S	

	More info >
<u></u>	
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >
· · · · · · · · · · · · · · · · · · ·	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-16
Last registration	2023-04-17
Complete history	See info



Registration #1	2010-11-16	13 mi
Registration #2	2013-08-01	11.729 mi
Registration #3	2014-06-05	20.017 mi
Registration #4	2015-08-06	39.148 mi
Registration #5	2016-08-12	48.330 mi
Registration #6	2017-08-07	61.631 mi
Registration #7	2017-08-07	61.631 mi
Registration #8	2019-02-01	86.060 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



SM60CSZ report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1902 mm
Height	1488 mm
Length	5072 mm
Wheel base	3070 mm
Kerb weight	1940 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 25887595