



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-18
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	36
Total items failed	0

MOT #11	2023-06-05 12:28
MOT test number	773887688626
Result	✓ Passed
Next expiry date	2024-06-27
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General underbody corrosion

MOT #10	2022-06-28 12:30
MOT test number	841890228017
Result	✓ Passed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Nail in tyre
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Sum pan corroded

**MOT #9** 2022-06-28 11:32**MOT test number** 638805305097**Result** ✗ Failed**MAJOR** Nearside Front Battery insecure and likely to fall from carrier (4.13 (a) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Sum pan corroded**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #8** 2021-06-19 11:10**MOT test number** 950457808446**Result** ✓ Passed**MOT #7** 2020-03-24 13:23**MOT test number** 297867217890**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced front subframe (6.1.1 (c) (i))**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**Advice** Oil leak, but not excessive engine sump corroded (8.4.1 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))

**MOT #6** 2020-03-23 09:29**MOT test number** 295069524756**Result** ✗ Failed**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced front subframe (6.1.1 (c) (i))**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive engine sump corroded (8.4.1 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2019-03-02 10:00**MOT test number** 571169114546**Result** ✓ Passed**MOT #4** 2019-02-25 16:45**MOT test number** 609806404753**Result** ✗ Failed**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))



MOT #3	2018-03-13 14:08
MOT test number	785905256490
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear tyre ON the legal limit of 16mm

MOT #2	2017-03-07 16:10
MOT test number	570593795006
Result	✓ Passed

MOT #1	2016-03-14 10:22
MOT test number	598387544777
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
27 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-22
Last registration	2023-06-05
Complete history	See info



Registration #1	2013-03-22	18 mi
Registration #2	2016-03-14	38.530 mi
Registration #3	2017-03-07	62.560 mi
Registration #4	2018-03-13	82.753 mi
Registration #5	2019-02-25	94.825 mi
Registration #6	2019-03-02	94.825 mi
Registration #7	2020-03-23	99.301 mi
Registration #8	2020-03-23	99.301 mi
Registration #9	2020-03-23	99.301 mi
Registration #10	2020-03-23	99.301 mi
Registration #11	2020-03-23	99.301 mi
Registration #12	2020-03-23	99.301 mi
Registration #13	2020-03-23	99.301 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0272619