



ND08ZNA

report date: 2024-03-29

General information

Make	KIA
Model	CARENS GS5 CRDI
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	163 g/km
CO2 label	G





MOT history

MOT expiry date	2024-04-18
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #15 2023-04-18 13:56

MOT test number 946948219910

Result ✓ Passed

Next expiry date 2024-04-18

- Advice** Rear Surface corrosion on rear suspension
- Advice** Front Surface corrosion on front suspension
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14 2023-04-14 11:47

MOT test number 717976293379

Result ✗ Failed

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Surface corrosion on rear suspension
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Surface corrosion on front suspension
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #13** 2022-03-22 10:42**MOT test number** 918657415011**Result** ✓ Passed**MOT #12** 2021-03-24 14:27**MOT test number** 253639721138**Result** ✓ Passed**MOT #11** 2020-04-06 13:23**MOT test number** 349092737136**Result** ✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both lower Arm front bushes are worn (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10 2020-04-06 08:14**MOT test number** 940935331146**Result** ✗ Failed

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both lower Arm front bushes are worn (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9** 2019-04-01 08:07**MOT test number** 260012852583**Result** ✓ Passed**Advice** Rear Coil spring corroded both. (5.3.1 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both. (5.2.3 (e))**MOT #8** 2018-04-11 07:50**MOT test number** 469569541478**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #7** 2017-04-19 09:40**MOT test number** 262181474155**Result** ✓ Passed**Advice** Front exhaust mount system still supported**MOT #6** 2016-03-21 13:09**MOT test number** 380904789451**Result** ✓ Passed**MOT #5** 2015-04-08 12:18**MOT test number** 315008795011**Result** ✓ Passed**Notice** Front exhaust clamp broken.**MOT #4** 2014-04-03 10:33**MOT test number** 208683194025**Result** ✓ Passed



MOT #3	2013-04-09 08:49
MOT test number	737249893064
Result	✓ Passed
MOT #2	2012-03-29 12:17
MOT test number	349819082080
Result	✓ Passed
MOT #1	2011-04-05 15:02
MOT test number	737695491063
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 August 2023

X

MOT

Expired:
18 April 2024

Tax status	Expired at 31 August 2023
Days left	241 days too late
MOT expiry date	18 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-05-19
Last registration	2023-04-18
Complete history	See info



Registration #1	2008-05-19	11 mi
Registration #2	2011-04-05	7.540 mi
Registration #3	2012-03-29	16.364 mi
Registration #4	2013-04-09	27.220 mi
Registration #5	2014-04-03	36.743 mi
Registration #6	2015-04-08	44.954 mi
Registration #7	2016-03-21	52.064 mi
Registration #8	2017-04-19	59.253 mi
Registration #9	2018-05-20	66.443 mi
Registration #10	2019-06-20	73.633 mi
Registration #11	2020-07-20	80.823 mi
Registration #12	2021-08-20	88.013 mi
Registration #13	2022-09-20	95.203 mi
Registration #14	2023-10-20	102.393 mi
Registration #15	2024-11-20	109.583 mi
Registration #16	2025-12-20	116.773 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1631 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4EA8H382090