





report date: 2024-03-28

### General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.988 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT histo	orv
-----------	-----

MOT expiry date	2024-11-12
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #14		2023-11-07 10:50
MOT test	number	769616357978
Result		✓ Passed
Next expi	ry date	2024-11-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2022-11-11 13:31
MOT test number	849585628056
Result	✓ Passed
MOT #12	2021-10-20 15:20
MOT test number	391719530493
Result	✓ Passed

2020-11-13 09:12
409025496935
✓ Passed

CarCheck.co.uk page 2/11



report date: 2024-03-28

**MOT #10** 2020-11-12 11:29

MOT test number 895846795528

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #9 2019-05-14 08:33

**MOT test number** 962916640197

**Result** 
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing outer edges (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened corroded and lipped (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**Advice** Under tray fitted

MOT #8 2018-03-08 10:12

**MOT test number** 317850003805

**Result** ✓ Passed

**Advice** Offside rear tyre wearing on inner edge

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #7		2017-03-01 17:14
MOT test nui	mber	852651259618
Result		✓ Passed
<b>Advice</b> Bo	olt in o/s/r tyre	
<b>Advice</b> O	/s/f tyre wearing on inner edge	

Advice	Bolt in o/s/r tyre	
<b>Advice</b> (	D/s/f tyre wearing on inner edge	
MOT #6		2016-02-12 11:50
MOT test nu	ımber	291345060073
Result		✓ Passed
MOT #5		2015-02-11 14:55
MOT test nu	ımber	157792045075
Result		<b>✓</b> Passed
MOT #4		2014-05-27 16:33
MOT test nu	ımber	668667944143
Result		<b>✓</b> Passed
MOT #3		2013-06-04 09:18
MOT test nu	imber	809675153147
Result		<b>✓</b> Passed
MOT #2		2012-06-06 09:57
MOT test nu	ımber	387728752137
Result		<b>✓</b> Passed
MOT #1		2011-06-21 14:20
MOT test nu	ımber	966542171157

MOT #1	2011-06-21 14:20
MOT test number	966542171157
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	12 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-06-25
Last registration	2023-11-07
Complete history	See info



Registration #1	2008-06-25	11 mi
Registration #2	2011-06-21	8.253 mi
Registration #3	2012-06-06	11.677 mi
Registration #4	2013-06-04	19.505 mi
Registration #5	2014-05-27	26.336 mi
Registration #6	2015-02-11	30.263 mi
Registration #7	2016-02-12	32.854 mi
Registration #8	2017-03-01	36.074 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

## Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0806030302416G

CarCheck.co.uk page 11/11