



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Grey
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-07
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-16
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	32
Total items failed	18

MOT #17	2022-06-10 11:24
MOT test number	736104258310
Result	✓ Passed
Next expiry date	2023-06-16
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2022-06-10 11:24
MOT test number	398640115601
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2021-06-17 13:49

**MOT test number**

806672505315

**Result**

✓ Passed

- Minor** Offside Rear All position lamps with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases middle (6.1.2 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2020-07-28 09:27

**MOT test number**

140403820116

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases Centre exhaust pipe has slight leak (6.1.2 (a))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush perished/split (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases Rear exhaust box has slight leak (6.1.2 (a))
- Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush perished/split (5.3.4 (a) (i))
- Advice** Front Oil leak, but not excessive Engine has slight oil leak (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Rear Inner All position lamps with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #13** 2019-08-02 15:15**MOT test number** 520821754611**Result** ✓ Passed**MOT #12** 2019-08-02 10:23**MOT test number** 847765260508**Result** ✗ Failed**Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Exhaust emissions likely to be affected by an induction leak (8.2.2.1 (b))**MOT #11** 2018-08-02 15:29**MOT test number** 176125195953**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2018-08-02 09:00**MOT test number** 575528500232**Result** ✗ Failed**Fail** Nearside Front Road wheel fixing missing wheel nut (5.2.1 (a) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2017-08-02 09:47**MOT test number** 481406282593**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-07-26 11:54**MOT test number** 656117523710**Result** ✓ Passed**MOT #7** 2015-07-09 16:35**MOT test number** 106520995135**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-06-28 12:42**MOT test number** 716429574124**Result** ✓ Passed**Advice** Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-06-21 15:20**MOT test number** 367872773134**Result** ✓ Passed**Notice** Steering wheel has knocking noise

**MOT #4** 2013-06-19 12:30**MOT test number** 587660073107**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Notice** Steering wheel has knocking noise**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Front Steering rack gaiter split (2.2.D.2d)**Advice** Nearside Front Steering rack gaiter deteriorated (2.2.D.2d)**Fail** Offside Outer Rear position lamp(s) not working (1.1.A.3b)**Fail** Centre Rear Stop lamp not working (1.2.1b)**Fail** Power steering malfunctioning (2.3.3a)**MOT #3** 2012-06-13 14:40**MOT test number** 956485162163**Result** ✓ Passed**MOT #2** 2012-06-13 11:16**MOT test number** 316925462196**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2011-05-21 16:28**MOT test number** 256051641446**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
11 April 2023

X

MOT

Expired:  
16 June 2023

Tax status	Expired at 11 April 2023
Days left	384 days too late
MOT expiry date	16 June 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-04
Last registration	2022-06-10
Complete history	<a href="#">See info</a>



Registration #1	2008-03-04	18 mi
Registration #2	2011-05-21	43.281 mi
Registration #3	2012-06-13	48.847 mi
Registration #4	2012-06-13	48.848 mi
Registration #5	2013-06-19	55.138 mi
Registration #6	2013-06-21	55.138 mi
Registration #7	2014-06-28	59.719 mi
Registration #8	2015-07-09	65.008 mi
Registration #9	2016-07-26	72.127 mi
Registration #10	2017-08-02	76.241 mi
Registration #11	2018-08-02	76.241 mi
Registration #12	2019-08-02	76.241 mi
Registration #13	2020-08-02	76.241 mi
Registration #14	2021-08-02	76.241 mi
Registration #15	2022-08-02	76.241 mi
Registration #16	2023-08-02	76.241 mi
Registration #17	2024-08-02	76.241 mi
Registration #18	2025-08-02	76.241 mi
Registration #19	2026-08-02	76.241 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	8R43181