





report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Red
Year of manufacture	2009
Top speed	102 mph
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-01-30

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	25
Total items failed	2

MOT #15	2023-05-02 11:28
MOT test number	701326206722
Result	✓ Passed
Next expiry date	2024-05-25

MOT #14		2022-05-19 10:36
MOT test	number	933318573738
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #13	2021-05-26 11:27
MOT test number	745188324042
Result	✓ Passed
Advice Nearside Front tyre slightly worn inner edge	
Minor Front Windscreen wiper blade defective both (3.4 (b) (i))	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping	g effect (5.3.2 (b))

MOT #12	2020-10-22 10:32
MOT test number	299533027635
Result	✓ Passed

CarCheck.co.uk page 3/13



 MOT #11
 2020-01-15 14:59

 MOT test number
 682612434903

 Result
 ✓ Passed

 MOT #10
 2020-01-15 09:38

 MOT test number
 382830579043

 Result
 X Failed

 MAJOR
 Offside Front Brake pipe excessively damaged (1.1.11 (c))

MOT #9		2019-01-23 09:15
MOT test	number	526810259066
Result		✓ Passed
MOT #8		2018-01-30 14:05
MOT test	number	243558977947
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7		2017-01-31 13:27
MOT test	number	693857016980
Result		✓ Passed
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Nearside Rear wheel bearing has slight play (2.6.2)	
Advice	N/s wiper rubber split on end	

CarCheck.co.uk page 4/13



MOT #6 2017-01-31 09:22

MOT test number 549249477412

Result X Failed

Advice Nearside Rear wheel bearing has slight play (2.6.2)

Advice Front suspect brake pads wearing low

Fail Central Stop lamp not working high level (1.2.1b)

Advice N/s wiper rubber split on end

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Rear tyre becoming low on tread2+mm; perished/cracked between tread

MOT #5 2016-01-25 12:58

MOT test number 806232823022

Result \rightarrow Passed

Advice Nearside Front tyre cuts in tread

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear tyre cuts in tread

MOT #4 2014-04-29 11:27

MOT test number 479889314157

Result \rightarrow Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



Advice

BJO9RTU report date: 2024-03-29

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

Result

Notice Front wiper blades starting to split

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2012-05-01 12:14

 MOT test number
 936062922122

 Result
 ✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NEW
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-26
Last registration	2023-05-02
Complete history	See info



Registration #1	2009-06-26	23 mi
Registration #2	2012-05-01	15.688 mi
Registration #3	2013-04-27	21.152 mi
Registration #4	2014-04-29	29.150 mi
Registration #5	2014-04-29	29.150 mi
Registration #6	2016-01-25	40.619 mi
Registration #7	2017-01-31	45.818 mi
Registration #8	2017-01-31	45.818 mi
Registration #9	2018-01-30	49.844 mi
Registration #10		
Tegistiation #10		
Registration #11		13,377 es
		10,777 es
Registration #11		11.777 es 11.777 es 11.777 es
Registration #11 Registration #12		11.777-00 11.777-00 11.777-00
Registration #11 Registration #12 Registration #13		10,777-66 10,777-66 10,777-66 10,777-66
Registration #11 Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 9B68714