



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI 16V
Colour	Silver
Year of manufacture	2006
Top speed	135 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	220 Nm at 3.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-21
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	48
Total items failed	19

MOT #242023-09-15 09:59

MOT test number327357922471

Result✓ Passed

Next expiry date2024-09-15

- AdviceRear brake discs corroded
- AdviceCorrosion to underside of vehicle
- AdviceExhaust front flexi deteriorated
- AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceDamage to front of vehicle
- AdviceExhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #23**

2023-09-14 11:26

MOT test number

351933247203

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Obligatory mirror missing (3.3 (a))
- Fail** Front Registration plate inscription illegible damaged (0.1 (b))
- Advice** Exhaust front flexi deteriorated
- Advice** Damage to front of vehicle
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear brake discs corroded
- Advice** Corrosion to underside of vehicle

MOT #22

2022-09-13 08:23

MOT test number

527336898193

Result**✓ Passed****MOT #21**

2022-09-13 08:23

MOT test number

651176565635

Result**✗ Failed**

- Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

MOT #20

2021-09-16 08:41

MOT test number

609192463275

Result**✓ Passed**

**MOT #19** 2021-09-14 13:38**MOT test number** 486604509617**Result** ✗ Failed**Fail** Rear Anti-roll bar pin or bush excessively worn both (5.3.4 (a) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #18** 2021-04-23 13:54**MOT test number** 708176187168**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #17** 2021-04-23 09:23**MOT test number** 985833435491**Result** ✗ Failed**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #16** 2020-05-14 10:11**MOT test number** 544557686651**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15**

2019-05-09 13:49

MOT test number

948027236038

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm worn on inner edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm worn on inner edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14

2019-05-07 15:31

MOT test number

452007820082

Result

✗ Failed

- Fail** Brake pipe excessively corroded front to rear by fuel tank x2 (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm worn on inner edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm worn on inner edge (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #13** 2018-04-20 12:02**MOT test number** 896616617750**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front coil spring corroded both (2.4.C.1b)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12 2017-05-05 09:35**MOT test number** 212978594425**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #11 2016-04-22 14:34**MOT test number** 667035250318**Result** ✓ Passed**MOT #10** 2015-04-24 15:17**MOT test number** 518534315168**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-04-24 10:25**MOT test number** 299514815161**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-04-11 12:50**MOT test number** 499111504127**Result** ✓ Passed**Notice** Both rear tyres scrubbing on inside edges**MOT #7** 2013-04-16 13:54**MOT test number** 925636903133**Result** ✓ Passed**MOT #6** 2012-04-20 15:44**MOT test number** 368511912169**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-04-19 16:29**MOT test number** 255190312169**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #4** 2011-04-18 09:26**MOT test number** 655438801172**Result** ✓ Passed**MOT #3** 2010-04-20 11:14**MOT test number** 391110910157**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-04-25 11:15**MOT test number** 441875119154**Result** ✓ Passed**MOT #1** 2009-04-22 09:59**MOT test number** 313002819159**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-05-09
Last registration	2023-09-15
Complete history	See info



Registration #1	2006-05-09	14 mi
Registration #2	2009-04-22	34.127 mi
Registration #3	2009-04-25	34.133 mi
Registration #4	2010-04-20	42.293 mi
Registration #5	2011-04-18	48.353 mi
Registration #6	2012-04-19	54.857 mi
Registration #7	2012-04-20	54.857 mi
Registration #8	2013-04-16	66.376 mi
Registration #9	2014-04-11	74.326 mi
Registration #10	2015-04-24	84.589 mi
Registration #11	2015-04-24	84.592 mi
Registration #12	2016-04-22	93.442 mi
Registration #13	2017-05-05	102.259 mi
Registration #14	2018-05-05	111.111 mi
Registration #15	2019-05-05	120.000 mi
Registration #16	2020-05-05	128.889 mi
Registration #17	2021-05-05	137.778 mi
Registration #18	2022-05-05	146.667 mi
Registration #19	2023-05-05	155.556 mi
Registration #20	2024-05-05	164.444 mi
Registration #21	2025-05-05	173.333 mi
Registration #22	2026-05-05	182.222 mi
Registration #23	2027-05-05	191.111 mi
Registration #24	2028-05-05	200.000 mi
Registration #25	2029-05-05	208.889 mi
Registration #26	2030-05-05	217.778 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	11587444