



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





## MOT history

MOT expiry date	2024-09-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	41
Total items failed	2

## MOT #13 2023-09-15 13:23

MOT test number 345121440129

Result ✓ Passed

Next expiry date 2024-09-15

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pipe clips or supports missing, pipe adequately supported Flexi pipe and hand brake bracket corroded through but pipes still secure (1.1.11 (d) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside front macpherson strut top mount looks seated wrong

## MOT #12 2022-09-15 15:07

MOT test number 986034840477

Result ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe clips or supports missing, pipe adequately supported Where the handbrake cable is fixed the bracket is corroded through but still secure (1.1.11 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



**MOT #11** 2021-09-16 14:16**MOT test number** 283154878051**Result** ✓ Passed**MOT #10** 2019-11-14 10:40**MOT test number** 610736185300**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre 2x nails
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2019-11-14 10:40**MOT test number** 658010583169**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Nail in tyre 2x nails
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2018-07-30 11:40**MOT test number** 958474456662**Result** ✓ Passed**MOT #7** 2017-08-11 12:28**MOT test number** 145729348142**Result** ✓ Passed

- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Central Rear Exhaust has a minor leak of exhaust gases rear box badly corroded and slight leak from centre exhaust (7.1.2)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt slight leak (2.5.C.1a)

**MOT #6** 2017-08-11 12:27**MOT test number** 580143382581**Result** ✗ Failed**Advice** Central Rear Exhaust has a minor leak of exhaust gases rear box badly corroded and slight leak from centre exhaust (7.1.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt slight leak (2.5.C.1a)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #5** 2016-08-11 11:03**MOT test number** 553400037467**Result** ✓ Passed**MOT #4** 2015-07-24 10:44**MOT test number** 827975105291**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-08-12 12:57**MOT test number** 479324824296**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2013-07-26 15:03**MOT test number** 505207803233**Result** ✓ Passed



MOT #1	2012-07-23 14:58
MOT test number	197055702206
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>GV09UCX</b>
Plate since	2024-03-29
Current registration	<b>GV09UCX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-08-18
Last registration	2023-09-15
Complete history	<a href="#">See info</a>



Registration #1	2009-08-18	23 mi
Registration #2	2012-07-23	20.201 mi
Registration #3	2013-07-26	27.551 mi
Registration #4	2014-08-12	34.358 mi
Registration #5	2015-07-24	41.169 mi
Registration #6	2016-08-11	48.695 mi
Registration #7	2017-08-11	55.269 mi
Registration #8	2018-08-11	61.843 mi
Registration #9	2019-08-11	68.417 mi
Registration #10	2020-08-11	74.991 mi
Registration #11	2021-08-11	81.565 mi
Registration #12	2022-08-11	88.139 mi
Registration #13	2023-08-11	94.713 mi
Registration #14	2023-09-15	101.287 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434