



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC70 D5 SE SPORT
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 3

Date 2021-12-03

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-11-07

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-10-15

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-11
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #17	2023-01-12 11:54
MOT test number	878759999056
Result	✓ Passed
Next expiry date	2024-01-11

MOT #16	2021-12-10 14:51
MOT test number	951842565315
Result	✓ Passed

MOT #15	2021-12-10 07:41
MOT test number	659658897788
Result	✗ Failed

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #14** 2021-07-23 12:37**MOT test number** 199847007410**Result** ✓ Passed**Advice** Offside Front Anti-roll bar ball joint has slight play link (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play link (5.3.4 (a) (i))**MOT #13** 2021-07-23 10:18**MOT test number** 180798809677**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar ball joint has slight play link (5.3.4 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Anti-roll bar ball joint has slight play link (5.3.4 (a) (i))**MOT #12** 2020-07-27 13:19**MOT test number** 404162626625**Result** ✓ Passed**MOT #11** 2019-07-16 08:50**MOT test number** 798084498232**Result** ✓ Passed**MOT #10** 2018-07-19 09:33**MOT test number** 299700342231**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Undertrays fitted obscuring some underside components**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2017-07-20 09:29**MOT test number** 359772665226**Result** ✓ Passed**MOT #8** 2016-07-19 08:52**MOT test number** 879326091690**Result** ✓ Passed**Advice** Offside front tyre wearing on inside edge**MOT #7** 2015-07-21 16:38**MOT test number** 738192205205**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2014-08-15 11:03**MOT test number** 776227224256**Result** ✓ Passed**MOT #5** 2013-04-19 09:26**MOT test number** 497329103147**Result** ✓ Passed**MOT #4** 2012-04-05 09:59**MOT test number** 866886992008**Result** ✓ Passed**MOT #3** 2012-03-30 09:03**MOT test number** 106530792021**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #2	2011-03-25 09:49
MOT test number	758754481003
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #1	2010-03-11 11:41
MOT test number	152360070017
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✗
MOT

Expired:
11 January 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	11 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-15
Last registration	2023-01-12
Complete history	See info



Registration #1	2007-03-15	25 mi
Registration #2	2010-03-11	10.084 mi
Registration #3	2011-03-25	13.844 mi
Registration #4	2012-03-30	17.499 mi
Registration #5	2012-04-05	17.499 mi
Registration #6	2013-04-19	21.267 mi
Registration #7	2014-08-15	26.711 mi
Registration #8	2015-07-21	30.906 mi
Registration #9	2016-07-19	37.582 mi
Registration #10	2017-07-20	44.930 mi
Registration #11	2018-07-19	50.661 mi
Registration #12	2019-07-19	55.392 mi
Registration #13	2020-07-19	60.123 mi
Registration #14	2021-07-19	64.854 mi
Registration #15	2022-07-19	69.585 mi
Registration #16	2023-01-12	74.316 mi
Registration #17		
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	432080