



RENAULT

RJIEHM


report date: 2024-03-28

General information

Make	RENAULT
Model	LAGUNA EXPRESSION DCI FAP
Colour	Black
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-07-03
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	57
Total items failed	8

MOT #14	2023-11-28 16:23
MOT test number	260878174841
Result	✓ Passed
Next expiry date	2024-12-20

MOT #13	2023-11-28 10:14
MOT test number	769516872443
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12	2022-12-21 16:09
MOT test number	604768182134
Result	✓ Passed
Advice	Front Suspension arm corroded but not seriously weakened ns/os/ w.bones (5.3.3 (b) (i))



MOT #11

2021-03-26 13:41

MOT test number

335985984183

Result

✓ Passed

- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice

Slight travel on handbrake lever
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Under trays fitted

**MOT #10**

2021-03-26 09:29

MOT test number

469835984301

Result

✗ Failed

- Advice** Slight travel on handbrake lever
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Under trays fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MOT #9

2020-03-14 17:12

MOT test number

304551602321

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))

**MOT #8**

2020-03-14 10:19

MOT test number

404147599427

Result

✗ Failed

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**MOT #7**

2019-03-16 10:17

MOT test number

263677806991

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6**

2018-03-31 08:43

MOT test number

915786433923

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays fitted**Advice** Both rear tyres cracking and perishing**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #52017-04-29 15:14

MOT test number198475790080

Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Bonnet catch sticking	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Both front tyres cut on outer walls but no cords showing	
Advice	Damage to outer body all over	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Both front tyres scrubbing on outer edges	
Advice	Both rear tyres + n/s/f tyres perishing and cracking	
Advice	Both front wipers slightly smudging windscreen but still clearing windscreen	

**MOT #4** 2017-04-29 09:56**MOT test number** 322611467015**Result** ✗ Failed

- Advice** Damage to outer body all over
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Both front tyres scrubbing on outer edges
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Both rear tyres + n/s/f tyres perishing and cracking
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Both front wipers slightly smudging windscreen but still clearing windscreen
- Advice** Bonnet catch sticking
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Both front tyres cut on outer walls but no cords showing
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2016-04-25 08:42**MOT test number** 437712617729**Result** ✓ Passed**MOT #2** 2015-05-07 14:26**MOT test number** 979857025112**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-05-08 13:12
MOT test number	976968924154
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	REXXXX
Plate since	2019-01-01
Current registration	REXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-23
Last registration	2023-11-28
Complete history	See info



Registration #1	2011-06-23	15 mi
Registration #2	2014-05-08	55.161 mi
Registration #3	2015-05-07	62.230 mi
Registration #4	2016-04-25	67.636 mi
Registration #5	2017-04-29	73.450 mi
Registration #6	2017-04-29	73.450 mi
Registration #7	2018-03-31	77.729 mi
Registration #8	2019-03-16	82.166 mi
Registration #9	2019-03-16	82.166 mi
Registration #10	2019-03-16	82.166 mi
Registration #11	2019-03-16	82.166 mi
Registration #12	2019-03-16	82.166 mi
Registration #13	2019-03-16	82.166 mi
Registration #14	2019-03-16	82.166 mi
Registration #15	2019-03-16	82.166 mi
Registration #16	2019-03-16	82.166 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4801 mm
Wheel base	2758 mm
Kerb weight	1418 kg
Max. allowed weight	1957 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D013562