





report date: 2024-03-29

General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Blue
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-21

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-04

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-11-06
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #10	2023-10-30 16:02
MOT test number	151330657632
Result	✓ Passed
Next expiry date	2024-11-06

MOT #9	2023-10-30 09:53
MOT test number	774876926653
Result	X Failed
Fail Horn not working (7.7 (a))	

MOT #8		2022-11-07 12:35
MOT test	number	879457099967
Result		✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



Result

SF16FHV

report date: 2024-03-29

✓ Passed

2022-11-07 12:35 **MOT #7** 829637671340 **MOT** test number Result × Failed **Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6 2021-12-23 10:04
MOT test number 496152293401
Result ✓ Passed

MOT #5 2021-06-24 13:31
MOT test number 588072995559

Result Passed

MOT #4 2021-06-24 13:31
MOT test number 588842932940

Result × Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

 MOT #3
 2020-06-18 13:22

 MOT test number
 720221100609

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2020-06-18 11:13

MOT test number 778297852867

Result

× Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #1 2019-06-19 11:35

MOT test number 126598757884

Result
✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge lowest tread depth = 3mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge tread depth = 3mm (5.2.3 (e))


Advice Nearside Front Tyre worn close to legal limit/worn on edge tread depth = 3mm (5.2.3 (e))

CarCheck.co.uk page 5/12



SF16FHV report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-07-07
Last registration	2023-10-30
Complete history	See info



Registration #1	2016-07-07	11 mi
Registration #2	2019-06-19	22.720 mi
Registration #3	2020-06-18	29.909 mi
Registration #4	2020-06-18	29.909 mi
Registration #5	2021-06-24	36.957 mi
Registration #6	2021-06-24	36.957 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	53
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

JBHB3076096